
HVAC and Refrigeration \ Air Filters \ Paint Collector Filter Pads and Rolls \ Paint Collector Filter Pads \ 20x20x2, Paint Collector Filter Pad, 15 Grams Fiberglass, Package Quantity 50

Print Email

View Product Family



20x20x2, Paint Collector Filter Pad, 15 Grams Fiberglass, Package Quantity 50

AIR HANDLER

Price ® \$47.35 / pkg. of 50	Deliver one time only Auto-Reorder Every 1 Month	Confirm ZIP Code to determine availability.		
	4	ZIP Code	1	
	Add to Cart	43085	Save	
	+ Add to List	· · · · · · · · · · · · · · · · · · ·		
ជំជាជ់ជំជា Beth	e first to write a review Ask & Answer	4500 March 1 - 1000 M		
នៃជាជាជាជា Be th	e first to write a review Ask & Answer Mfr. Model # 2W001	UNSPSC # 4016	1524	

Note: Product availability is real-time updated and adjusted continuously. The product will be reserved for you when you complete your order. More

Technical Specs

Item	Paint Collector Filter Pad	p	Nominal Width	20"
Media	15 Grams Fiberglass		Nominal Depth	2"
Nominal Filter Size	20x20x2		Standards	EPA, NFPA #33, OSHA #1910.107
Nominal Height	20"			

question #6

QUESTIONS 12,13

WELDING V	WELDING WIRE USED SINCE 9/1/2010		QUESTIONS 12 &13		
WIRE		DESCRIPTION	POUNDS	MONTLY AVG.	
70S6035	1	SOLID WIRE	23495	391.58	
71T1045	2	.045 FLUX CORE	2664	44.40	
KOB309L	3	FLUX CORE	280	4.67	
SVK316LSI	4	SOLID WIRE	132	2.20	
		, , , , , , , , , , , , , , , , , , , ,		- A II-107 - A II-107 - A	



MSDS No.: US01-04 (Rev.2) Issue Date: Jul.23, 2008

MATERIAL SAFETY DATA SHEET (MSDS)

(2 pages)

For Welding Consumables and Related Products
Complies with OSHA Hazard Communication Standard 29 C.F.R. 1910.1200

SECTION I -	IDENTIFICATION
Identity: KOBELCO ELECTRODES FOR GAS SHIELDED A	
Manufacture's Name: KOBE STEEL, LTD. Supplier's Name: KOBE STEEL, LTD.	Emergency Telephone No: +81-3-5739-6331
Supplier's Address: 5-9-12 Kitashinagawa Shinagawa-Ku Tokyo JAPAN	Telephone No. for Information: +81-3-5739-6331 Facsimile No. : +81-3-5739-6960
Product Trade Designation	Product Classifications
MG-51T SE-A50 MG-50T	AWS A.518 ER70S-6 AWS A.518 ER70S-G

SECTION II - HAZARDOUS INGREDIENTS

IMPORTANT: THIS SECTION COVERS THE MATERIALS FROM WHICH THE PRODUCT IS MANUFACTURED. THE FUMES AND GASES PRODUCED DURING WELDING WITH NORMAL USE OF THIS PRODUCT ARE COVERED IN SECTION V.

THE TERM "HAZARDOUS" IN "HAZARDOUS MATERIALS" SHOULD BE INTERPRETED AS A TERM REQUIRED AND DEFINED IN OSHA HAZARD COMMUNICATION STANDARD (29 C.F.R. 1910.1200) AND IT DOES NOT NECESSARILY IMPLY THE EXISTENCE OF ANY HAZARD.

Ingredient	(CAS No.)	APPROX wt (%)	(1) TLV (mg/m ³)	/ Ingredient	(CAS No.)	APPROX wt (%)	(1) TLV (mg/m³)
Iron	(7439-89-6)	Balance	5	Copper	(7440-50-8)	≦0.50	(N/A)
Carbon	(7440-44-0)	≦0.15	(N/A)			11 0.00	, ,
Manganese	(7439-96-5)	≦1.85	0.2	· · · · · · · · · · · · · · · · · · ·		• • • • • • • • • • • • • • • • • • • •	
Silicon	(7440-21-3)	≦1.15	10				

(1) American Conference of Governmental Industrial Hygenists (ACGIH) Threshold Limit Value (TLV [R]).

SECTION III - PHYSICAL DATA

NOT APPLICABLE

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

Non-Flammable: Welding arc and sparks can ignite combustibles. See Z-49.1 referenced in Section VII.



MSDS No.: US01-04 (Rev.2) Issue Date: Jul.23, 2008

SECTION V - REACTIVITY DATA

HAZARDOUS DECOMPOSITION PRODUCTS:

Welding fumes cannot be classified simply. Their composition and quantity are dependent upon the metal being welded, the process, procedures and electrodes used. Other conditions which also influence the composition and quantity of the fumes and gases to which workers may be exposed include: coatings on the metal being welded (such as paint, plating, or galvanizing), number of welds and volume of work area, quality and amount of ventilation, position of welder's head with respect to thefume plume, as well as the presence of contaminants in the atmosphere (such as chlorinated hydrocarbon vapors from cleaning and degreasing activities).

When the electrode is consumed, the fume and gas decomposition products are different in percent and form from the ingredients listed in Section II. Fume and gas decomposition products, not the ingredients in the electrode, are important. Decomposition products include those originating from the volatilization, reaction, or oxidation of the materials shown in Section II plus those from base metal, coating, etc. as noted above. These components are virtually always present as complex compounds and not as metals (Characterization of Arc Welding Fume: American Welding Society).

Reasonably expected fume constituents from these products would include fluorides and complex oxides of iron, manganese, silicon, and, when present, nickel, chromium, molybdenum, and copper. Gaseous reaction products may include carbon monoxide and carbon dioxide. Ozone and nitrogen oxides may be formed by the radiation from the arc.

One recommended way to determine the composition and quantity of firmes and gases to which workers are exposed is to take an air sample inside the welders helmet, if worn, or in the worker's breathing zone. ANSI/AWS F1.1, available from the American Welding Society, P.O. Box 351040, Miami, FL 33135.

SECTION VI - HEALTH HAZARD DATA

Threshold Limit Value: The ACGIH recommended general limit for welding fume NOC (Not Otherwise Classified) is 5mg/m3. The ACGIH 1984-1985 preface states: "The TLV-TWA should be used as guides in the control of health hazards and should not be used as firm lines between safe and dangerous concentration." See Section V for specific fume constituents which may modify this TLV.

Effects of Overexposure: FUMES AND GASES can be dangerous to your health.

SHORT-TERM (ACUTE) OVEREXPOSURE to welding fumes may result in discomfort such as: dizziness, nausea, or dryness or irritation of nose, throat, or eves.

LONG TEAM (CHRONIC) OVEREXPOSURE may lead to siderosis (iron deposits in the lung) and is believed by some inves-tigators to affect pulmonary function.

ARC RAYS can injure eyes and burn skin.

ELECTRIC SHOCK can kill. See Section VII.

Emergency & First Aid Procedures: Call for medical aid. Employ first aid techniques recommended by the American Red Cross. Carcinogenicity: NOT APPLICABLE

SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE/APPLICABLE CONTROL MEASURES

Read and understand the manufacture's instructions and the precautionary label on this product. See American National Standard Z-49.1, Safety in Welding and Cutting, published by the American Welding Society, P.O. Box 351040, Miami, FL 33135 and OSHA Publication 2206 (29 C.F.R. 1910), U.S.Government Printing Office, Washington, D.C. 20402 for more detail on many of the following:

Ventilation: Use enough ventilation, local exhaust at the arc, or both, to keep the fumes and gases below the TLV's in the worker's breathing zone and the general area. Train the welder to keep his head out of the fumes.

Respiratory Protection: Use respirable fume respirator or air supplies repirator when welding in confined space or where local exhaust or ventilation does not keep exposure below TLV.

Eye Protection: Wear helmet or use face shield with filter lens. As a rule of thumb, start with a shade which is too dark to see the weld zone. Then go to the next lighter shade which gives sufficient view of the weld zone. Provide protective screens and flash goggles, if necessary, to shield others.

Protective Clothing: Wear head, hand and body protection which help to prevent injury from radiation, sparks and electrical shock. See ANSI Z-49.1. At a minimum, this includes welder's gloves and a protective face shield and may include arm protectors, aprons hats, shoulder protection, as well as dark substantial clothing. Train the welder not to touch live electrical parts and to insulate himself from work and ground.

Procedure for Cleanup of Spills or Leaks: NOT APPLICABLE

Waste Disposal Method: Prevent waste from contaminating surrounding environment. Discard any product, residue, disposable container, or liner in an environmentally acceptable manner, in full compliance with Federal. State and Local regulations

SAFETY DATA SHEET

Marketheres (Season Regulation)

Trade designation

DW-50

Recommended use

For welding

Restrictions on use

Do not use except for welding.

Manufacturer

Manufacturer's Name:

KOBE STEEL, LTD.

Address:

5-9-12 Kitashinagawa Shinagawa-Ku Tokyo JAPAN

Phone number:

+81-3-5739-6331 +81-3-5739-6960

Fax number: Emergency phone number:

Distributor's Name:

+81-3-5739-6331

Distributor

KOBELCO WELDING OF AMERICA INC.

Address:

4755 Alpine Rd. Ste 250 Stafford, Texas

Phone number: Fax number:

281-240-5600 281-240-5625

Emergency phone number:

281-240-5600

<u>PAHAANATAD SADDEN AHARANATON PA</u>

Classification according to OSHA Hazard Communication Standard (29 CFR 1910.1200) and the Canadian Controlled Products Regulations.

Hazard classification

Classification not possible as hazardous according to GHS classification.

Label elements

Symbol:

Not applicable

Signal word:

Not applicable

Hazard statement:

Not applicable

Precautionary statement:

Not applicable

Other hazards which do not classified in GHS classification

General:

When this product is used in a welding process the hazards are electric shock, fumes, gases, radiation, spatter, slag and heat. Read and understand this Safety Data Sheets and the manufacturer's instructions and the precautionary labels

before using this product.

Shock:

Electrical Shock can kill.

Radiation:

Arc rays can injure eyes and burn skin.

Fumes:

Overexposure to welding fumes result in symptoms like dizziness, nausea, dryness or irritation of the nose, throat or eyes. Chronic overexposure to welding fumes

may affect respiratory system and nervous system. Substance(s) formed under the conditions of use

The welding fumes produced from this welding electrode may contain the listed constituent(s) of Sec.3 and/or their complex metallic oxides as well as solid particles or other constituents from the consumables, base metal, or base metal coating not listed Sec.3. The welding fumes may contain Mn, Ni, Cr(VI) and

their compounds. Refer to Sec.8 and 10.

Gases: Gases may cause gas poisoning. Under conditions of use, gases may contain

carbon oxides, nitrogen oxides, ozone etc. Refer to Sec.8 and 10.

Spatter, slag:

Spatter, slag can damage eyes.

Heat:

Spatter, slag, melting metal, hot welds, are rays and sparks can cause burn injuries

and ignite combustibles and flammable materials

SDS No.: US-E DW-50 Format rev.0 / Data rev.0

Date of issue: 2015-05-20

ESCOMPONEUO VARROLAVATION O NAMERIORIAS ES

Substance/Mixture

Mixture

Chemical name	CAS No.	Concentration range (%)
Iron	7439-89-6	Balance
Titanium dioxide	13463-67-7	<10
Manganese	7439-96-5	< 3
Silicon	7440-21-3	<1
Silicon dioxide	7631-86-9	<1
Magnesium	7439-95-4	<1
Aluminum oxide	1344-28-1	< 1
Zirconium oxide	1314-23-4	<1

PAPERISTRATION TO A VERTICAL STATE OF THE PAPER STA

Description of first aid measures

Inhalation: Remove person to fresh air and keep comfortable for breathing and get medical

advice/attention. If breathing has stopped, perform artificial respiration and get immediate

medical advice/attention.

Skin contact: Take off contaminated clothing and rinse skin with soap and water [or shower]. If skin

irritation occurs, get medical advice/attention. For reddened or blistered skin, or thermal burns,

get medical advice/attention.

Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to Eye contact:

do. Continue rinsing. Get medical advice/attention.

Arc rays can injure eyes. If exposed to arc rays, move victim to dark room, remove contact lenses as necessary for treatment, cover eyes with a padded dressing and rest. If symptoms

persist, get medical advice/attention.

Disconnect and turn off power. If the victim is semi- or unconscious, open the airway. If the Electric shock:

victim cannot breath, give artificial respiration. If there is no pulse, massage the chest and

apply artificial respiration.

Ingestion: Unlikely due to form of product, except for granular materials. If ingested, Rinse mouth. Do

NOT induce vomiting. Immediately call a POISON CENTER/doctor.

Most important symptoms/effects, acute and delayed

Short-term (acute) overexposure to welding fumes may result in discomfort such as metal Symptoms:

fume fever, dizziness, nausea, or dryness or irritation of nose, throat, or eyes. May aggravate

pre-existing respiratory problems (e.g. asthma, emphysema).

Long-term (chronic) overexposure to welding fumes can lead to siderosis (iron deposits in lung), central nervous system effects, bronchitis and other pulmonary effects. Refer to Section

11 for more information.

Hazards: Welding hazards are complex and may include physical and health hazards such as but not

limited to electric shock, physical strains, radiation burns (eye flash), thermal burns due to hot metal or spatter and potential health effects of overexposure to welding fume or dust. Refer to

Section 11 for more information.

Indication of immediate medical attention and special treatment needed Treatment

Treat Symptomatically.

SATAK PED KORMUNYA MIDAKSKIR PER

General fire hazards

As shipped, this product is nonflammable. However, welding arc and sparks can ignite combustibles and flammable products. Read and understand American National Standard Z49.1, "Safety In Welding, Cutting and Allied Processes" before using this product.

Suitable (and unsuitable) extinguishing media

Suitable extinguishing media:

As shipped, the product will not burn. In case of fire in the surroundings,

use CO₂, powder or water spray. Unsuitable extinguishing media: None known

Specific hazards arising from the chemical

None known

Special protective equipment and precautions for fire-fighters

Special protective equipment: Selection of respiratory protection for fire-fighting: follow the general fire

precautions indicated in the workplace. Self-contained breathing apparatus

and full protective clothing must be worn in case of fire.

Special precautions: Use standard firefighting procedures and consider the hazards of other

involved materials.

General

Unlikely due to form of product, except for granular materials. The welding fumes and slags may be released.

Personal precautions, protective equipment and emergency procedures

If airborne dust and/or fume is present, use adequate engineering controls and, if needed, personal protection to prevent overexposure. Refer to recommendations in Section 8.

Methods and material for containment and cleaning up

Clean up spills immediately, observing precautions in the personal protective equipment in Section 8. Avoid generating dust. Prevent product from entering any drains, sewers or water sources. Refer to Section 13 for proper disposal.

Environmental precautions

Avoid release to the environment. Prevent further leakage or spillage if safe to do so.

7 PANDENCAND SPORACE

Precautions for safe handling

Reduction of fumes and dusts: Keep formation of airborne dusts to a minimum. Provide appropriate

exhaust ventilation at places were dust is formed. Read and understand the manufacturer's instruction and the precautionary label on the product. See American National Standard Z49.1, "Safety In Welding, Cutting and

Allied Processes"

Prevention of electric shock: Do not touch live electrical parts such as the welding wire and welding

machine terminals. Wear insulated gloves and safety boots. If welding must be performed in damp locations or with wet clothing, on metal structures or when in cramped positions such as sitting, kneeling or lying, or if there is a high risk of unavoidable or accidental contact with workpiece, use the following equipment: Semiautomatic DC Welder, DC Manual (Stick) Welder, or AC Welder with Reduced Voltage Control.

Remove flammable and combustible materials and liquids. Prevention of fire and explosion:

Prevention of harm when handling

Handle with care to avoid stings and cuts. Hold the welding wire welding consumables:

manually when loosening the wire.

Conditions for safe storage, including any incompatibilities

Store welding consumables inside a room without humidity. Do not store welding consumables directly on the ground or beside a wall. Keep welding consumables away from chemical substances like acids which could cause chemical reactions. Store in accordance with local/regional/national regulations.

STEASHOLSHILL CCCANTROL AT HARACTAT THOREGOE HAA

Control parameters

For substances may be included in welding fumes, gases and flux, occupational exposure values are shown in Annex. Keep exposure below exposure limits. Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs) are values published by the American Conference of Government Industrial Hygienists (ACGIH). ACGIH Statement of Positions Regarding the TLVs and BEIs states that the TLV-TWA should be used as a guide in the control of health hazards and should not be used to indicate a fine line between safe and dangerous exposures. See Section 10 for information on potential fume constituents of health interest.

Appropriate engineering controls

Ventilation:

Use enough ventilation, local exhaust at the arc, or both to keep the fumes and gases below the exposure limits in the worker's breathing zone and the general area. Keep exposure as low as possible.

Determine the composition and quantity of fumes and gases to which workers are exposed by taking an air sample from inside the welder's helmet if worn or in the

worker's breathing zone. Improve ventilation if exposures are not below limits. See ANSI/AWS F1.1, F1.2, F1.3 and F1.5, available from the American Welding Society warms are org.

Society, <u>www.aws.org</u>.

Individual protection measures

Eye protection: Wear helmet or use face shield with filter lens. As a rule of thumb, start with a shade

which is too dark to see the weld zone. Then go to the next lighter shade which gives sufficient view of the weld zone. Provide protective screens and flash goggles, if

necessary, to shield others.

Hand protection: Wear protective gloves. Suitable gloves can be recommended by the glove supplier.

Protective Clothing: Wear hand, head, and body protection which help to prevent injury from radiation,

sparks and electrical shock. See Z49.1. At a minimum this includes welder's gloves and a protective face shield, and may include arm protectors, aprons, hats, shoulder protection, as well as dark substantial clothing. Wear dry gloves free of holes or split seams. Train the welder not to permit electrically live parts or electrodes to contact skin or clothing or gloves if they are wet. Insulate yourself from the work piece and

ground using dry plywood, rubber mats or other dry insulation.

Respiratory protection: Keep your head out of fumes. Use enough ventilation and local exhaust to keep

fumes and gases from your breathing zone and the general area. Use respirable fume respirator or air supplied respirator when welding in confined space or where local

exhaust or ventilation does not keep exposure below exposure limits.

Ear protection: Wear earplugs or earmuffs when using engine driven arc welding machine or pulsed

arc welding machine that generates high-level

noise.

Hygiene measures: Do not eat, drink or smoke when using the product. Always observe good personal

hygiene measures, such as washing after handling the material and before eating, drinking, and/or smoking. Routinely wash work clothing and protective equipment

to remove contaminants.

9. PHYSICAL AND CHEMICAL PROPERTIES

Physical state: Solid

Color: Silver or Copper

Odorless Odorless

Odor threshold: No further relevant information available

pH: Not applicable

Melting point/freezing point:

No further relevant information available

No further relevant information available

No further relevant information available

Flash point: Not applicable Evaporation rate: Not applicable

Flammability: No further relevant information available Upper/lower flammability or explosive limits: No further relevant information available

Vapor pressure:Not applicableVapor density:Not applicable

Solubility(ies)

Partition coefficient (n-octanol/water):

Auto-ignition temperature:

No further relevant information available

Viscosity: Not applicable

TO STABILITY AND REACTIVITY

Reactivity

Non-reactive under normal conditions of storage and transport.

Chemical stability

Stable under normal conditions of storage and transport.

Possibility of hazardous reactions

Contact with acids, alkalis and oxidizing agents could cause reaction and generation of gas.

Conditions to avoid

Avoid heat or contamination of acids, alkalis and oxidizing agents.

SDS No.: US-E DW-50 Format rev.0 / Data rev.0

Date of issue: 2015-05-20

Incompatible materials

Avoid contact with acids, alkalis and oxidizing agents.

Hazardous decomposition products

Welding fumes and gases are generated as byproducts during the welding. The composition and quantity of fumes and gases cannot be recognized simply. The composition and quantity of the fumes and gases are dependent upon the base metal being welded (included coating such as solvent, paint, plating), the welding process, welding procedure, welding parameter and electrodes used. Other conditions which also influence the quantity of the fumes and gases to which workers may be exposed include the number of welding spots, the volume of the worker area, the quality and amount of ventilation, the position of the welder's head with respect to the fume plume, as well as the presence of contaminants in the atmosphere (such as chlorinated hydrocarbon vapors from cleaning and degreasing activities.)

The fumes and gases are different in percent and form from the ingredients listed in Section 3. The fumes and gases include those originating from the volatilization, reaction, or oxidation of the materials shown in Section 3, plus those from the base metal and coating, etc., as noted above. Reasonably expected fume constituents produced during arc welding include the oxides of iron, manganese and other metals present in the welding consumable or base metal. And, it is known that these metal oxides are complex oxides, not single compounds. Hexavalent chromium compounds may be in the welding fume of consumables or base metals which contain chromium. Nickel compounds may be in the welding fume of consumables or base metals which contain Nickel. Gaseous and particulate fluoride may be in the welding fume of consumables which contain fluoride. Gaseous reaction products may include carbon monoxide and carbon dioxide. Ozone and nitrogen oxides may be formed by the radiation from the arc.

TIL TONICOLO(ACATEMBORMANION

General

Classification not possible as product. Refer to Sec.2. Inhalation of welding fumes and gases can be dangerous to your health. The composition and quantity of both are dependent upon the material being worked, the process, procedures, and consumables used. Refer to Sec.10.

Acute toxicity

Short-term (acute) overexposure to welding fumes may result in discomfort such as metal fume fever, dizziness, nausea, or dryness or irritation of nose, throat, or eyes. May aggravate pre-existing respiratory problems (e.g. asthma, emphysema).

Cr: The presence of chromium/chromate in welding fumes can cause irritation of nasal membranes and skin.

Ni: The presence of nickel compounds in fume can cause metallic taste, nausea, tightness of chest, fever.

F: Exposure to the fluoride ion in welding fumes may cause hypocalcemia-calcium deficiency in the blood that can result in muscle cramps and inflammation and necrosis of mucous membranes.

Gases: Some toxic gases associated with welding may cause pulmonary edema, asphyxiation, and death.

Chronic toxicity

Long-term (chronic) overexposure to welding fumes can lead to siderosis (iron deposits in lung), central nervous system effects, bronchitis, pneumoconiosis and other pulmonary effects. The severity of the change is proportional to the length of the exposure. The changes may be caused by non-work factors such as smoking, etc.

Ni: Long term overexposure to nickel fumes may also cause pulmonary fibrosis and edema.

Cr: Chromates may cause ulceration, perforation of the nasal septum, and severe irritation of the bronchial tubes and lungs. Liver damage have also been reported. Chromates contain the hexavalent form of chromium.

Mn: Overexposure to manganese compounds may affect the central nervous system, symptoms of which are languor, sleepiness, muscular weakness, emotional disturbances and spastic gait. The effect of manganese on the nervous system is irreversible.

Cu: Overexposure to copper fumes may lead to copper poisoning, resulting in hermolytic anemia and liver, kidney and spleen damage.

Fe: Inhalation of too much iron oxide fume over a long time can cause siderosis, sometimes called "iron pigmentation" of the lung, which can be seen on a chest x-ray but causes little or no disability. Chronic overexposure to iron (>50-100mg Fe per day) can result in pathological deposition of iron in body tissues, symptoms of which are fibrosis of the pancreas, diabetes mellitus, and liver cirrhosis.

SiO₂: Respiratory exposure to the crystalline silica present in this welding electrode is not anticipated during normal use. Respiratory overexposure to airborne crystalline silica is known to cause silicosis, a form of disabling pulmonary fibrosis which can be progressive and may lead to death.

F: Chronic fluoride absorption can result in osseous fluorosis, increased radiographic density of the bones and mottling of the teeth.

Carcinogenicity

Welding fumes (not otherwise specified) are possibly carcinogenic to humans. Welding fumes is on the IARC lists as posing a cancer risk.

SiO₂: Crystalline silica is on the IARC (International Agency for Research on Cancer) and NTP (National Toxicology Program) lists as posing a cancer risk to humans.

Ni: Nickel and its compounds are on the IARC and NTP lists as posing respiratory cancer risk.

Cr: Hexavalent chromium and its compounds are on the IARC and NTP lists as posing a cancer risk to humans.

Are Skin cancer has been reported.

rays:

Respiratory or Skin Sensitization

Ni: Nickel and its compounds are skin sensitizers with symptoms ranging from slight itch to severe dermatitis.

Cr: Chromates may cause allergic reactions, including skin rash. Asthma has been reported in some sensitized individuals. Skin contact may result in irritation, ulceration, sensitization, and contact dermatitis.

Others

Organic polymers may be used in the manufacture of various welding consumables. Overexposure to their decomposition byproducts may result in a condition known as polymer fume fever. Polymer fume fever usually occurs within 4 to 8 hours of exposure with the presentation of flu like symptoms, including mild pulmonary irritation with or without an increase in body temperature. Signs of exposure can include an increase in white blood cell count. Resolution of symptoms typically occurs quickly, usually not lasting longer than 48 hours.

washirayayayayayayayayayayaya

Ecotoxicity

Product: No further relevant information available

Persistence and degradability

Product: No further relevant information available

Bioaccumulative potential

Product: No further relevant information available

Mobility in soil

Product: No further relevant information available

G DISPOSAL CONSIDERATIONS

The generation of waste should be avoided or minimized whenever possible. When practical, recycle in an environmentally acceptable, regulatory compliant manner. Dispose of non-recyclable products in accordance with all applicable National, State, and Local requirements. Discharge, treatment, or disposal may be subject to National, State, or Local laws.

GROWN WAS TRUITED BY A COLOR OF THE COLORS

UN number:
UN proper shipping name:
Not applicable
Transport hazard class(es):
Packing group:
Not applicable
Not applicable
Not applicable
Not applicable
Transport in bulk (according to Annex II of MARPOL73/78 and the IBC Code):
Special precautions for user:
Not applicable
Not applicable
Not applicable

I SURTRANDAY (ORANDAY FOR MATERIAL)

Regulations of each country are applied to subustance/mixures.

SECTION DE LA COMPANION DE LA

Reference

American National Standard (ANSI) Z49.1 "Safety in Welding, Cutting, and Allied Processes"

Date of issue

2015-05-20

Disclaimer

The information given in this SDS is based on the present level of our knowledge and experience. This information is believed to be accurate as of the revision date shown above. However, no warranty, expressed or implied, is given. Because the conditions or methods of use are beyond KOBE STEEL, LTD.'s control, we assume no liability resulting from the use of this product. Regulatory requirements are subject to change and may differ between various locations. Compliance with all applicable Federal, State, Provincial, and local laws and regulations remain the responsibility of the user. If necessary, consult an industrial hygienist or other expert to understand this information and safeguard the environment and protect workers from potential hazards associated with the handling or use of this product.

SDS No.: US-E DW-309L Format rev.0 / Data rev.0

Date of issue: 2015-05-20

SAFETY DATA SHEET

Trade designation

DW-309L

Recommended use

For welding

Restrictions on use

Do not use except for welding.

Manufacturer

Manufacturer's Name: KOBE STEEL, LTD.

Address: 5-9-12 Kitashinagawa Shinagawa-Ku Tokyo JAPAN

Phone number: +81-3-5739-6331 Fax number: +81-3-5739-6960 Emergency phone number: +81-3-5739-6331

Distributor

Distributor's Name: KOBELCO WELDING OF AMERICA INC. Address: 4755 Alpine Rd. Ste 250 Stafford, Texas

Phone number: 281-240-5600 Fax number: 281-240-5625 Emergency phone number: 281-240-5600

ZEHAZANDS TOTANETETCANIOA SE

Classification according to OSHA Hazard Communication Standard (29 CFR 1910.1200) and the Canadian Controlled Products Regulations.

Hazard classification

Classification not possible as hazardous according to GHS classification.

Label elements

Shock:

Symbol: Not applicable Signal word: Not applicable Not applicable Hazard statement: Precautionary statement: Not applicable

Other hazards which do not classified in GHS classification

When this product is used in a welding process the hazards are electric shock, General:

fumes, gases, radiation, spatter, slag and heat. Read and understand this Safety Data Sheets and the manufacturer's instructions and the precautionary labels

before using this product. Electrical Shock can kill.

Radiation: Arc rays can injure eyes and burn skin.

Fumes: Overexposure to welding fumes result in symptoms like dizziness, nausea, dryness

or irritation of the nose, throat or eyes. Chronic overexposure to welding fumes

may affect respiratory system and nervous system. Substance(s) formed under the conditions of use

The welding fumes produced from this welding electrode may contain the listed constituent(s) of Sec.3 and/or their complex metallic oxides as well as solid particles or other constituents from the consumables, base metal, or base metal coating not listed Sec.3. The welding fumes may contain Mn, Ni, Cr(VI) and

their compounds. Refer to Sec. 8 and 10.

Gases: Gases may cause gas poisoning. Under conditions of use, gases may contain

carbon oxides, nitrogen oxides, ozone etc. Refer to Sec.8 and 10.

Spatter, slag: Spatter, slag can damage eyes.

Heat: Spatter, slag, melting metal, hot welds, are rays and sparks can cause burn injuries

and ignite combustibles and flammable materials

SCOMPOSETION/INFORMATION ON INGREDIENTS

Substance/Mixture

Mixture

Chemical name	CAS No.	Concentration range (%)
Iron	7439-89-6	Balance
Chromium	7440-47-3	18-28
Nickel	7440-02-0	8-18
Silicon dioxide	7631-86-9	< 5
Manganese	7439-96-5	<3
Zirconium oxide	1314-23-4	< 3
Titanium dioxide	13463-67-7	<3
Aluminum oxide	1344-28-1	<1
Silicon	7440-21-3	<1
Sodium oxide	1313-59-3	<1
Magnesium oxide	1309-48-4	<1
Potassium oxide	12136-45-7	<1

THE BUILT OF A DESCRIPTION OF THE

Description of first aid measures

Inhalation: Remove person to fresh air and keep comfortable for breathing and get medical

advice/attention. If breathing has stopped, perform artificial respiration and get immediate

medical advice/attention.

Skin contact: Take off contaminated clothing and rinse skin with soap and water [or shower]. If skin

irritation occurs, get medical advice/attention. For reddened or blistered skin, or thermal burns,

get medical advice/attention.

Eye contact: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to

do. Continue rinsing. Get medical advice/attention.

Arc rays can injure eyes. If exposed to arc rays, move victim to dark room, remove contact lenses as necessary for treatment, cover eyes with a padded dressing and rest. If symptoms

persist, get medical advice/attention.

Electric shock: Disconnect and turn off power. If the victim is semi- or unconscious, open the airway. If the

victim cannot breath, give artificial respiration. If there is no pulse, massage the chest and

apply artificial respiration.

Ingestion: Unlikely due to form of product, except for granular materials. If ingested, Rinse mouth. Do

NOT induce vomiting. Immediately call a POISON CENTER/doctor.

Most important symptoms/effects, acute and delayed

Symptoms: Short-term (acute) overexposure to welding fumes may result in discomfort such as metal

fume fever, dizziness, nausea, or dryness or irritation of nose, throat, or eyes. May aggravate

pre-existing respiratory problems (e.g. asthma, emphysema).

Long-term (chronic) overexposure to welding fumes can lead to siderosis (iron deposits in lung), central nervous system effects, bronchitis and other pulmonary effects. Refer to Section

11 for more information.

Hazards: Welding hazards are complex and may include physical and health hazards such as but not

limited to electric shock, physical strains, radiation burns (eye flash), thermal burns due to hot metal or spatter and potential health effects of overexposure to welding fume or dust. Refer to

Section 11 for more information.

Indication of immediate medical attention and special treatment needed Treatment

Treat Symptomatically.

ESTRUCTURE OF THE PROPERTY OF

General fire hazards

As shipped, this product is nonflammable. However, welding arc and sparks can ignite combustibles and flammable products. Read and understand American National Standard Z49.1, "Safety In Welding, Cutting and Allied Processes" before using this product.

Suitable (and unsuitable) extinguishing media

Suitable extinguishing media: As shipped, the product will not burn. In case of fire in the surroundings.

use CO₂, powder or water spray.

Unsuitable extinguishing media: None known Specific hazards arising from the chemical

None known

Special protective equipment and precautions for fire-fighters

Special protective equipment: Selection of respiratory protection for fire-fighting: follow the general fire

precautions indicated in the workplace. Self-contained breathing apparatus

and full protective clothing must be worn in case of fire.

Special precautions: Use standard firefighting procedures and consider the hazards of other

involved materials.

KORTO O DE LA COLOR DE LA COLO

General

Unlikely due to form of product, except for granular materials. The welding fumes and slags may be released.

Personal precautions, protective equipment and emergency procedures

If airborne dust and/or fume is present, use adequate engineering controls and, if needed, personal protection to prevent overexposure. Refer to recommendations in Section 8.

Methods and material for containment and cleaning up

Clean up spills immediately, observing precautions in the personal protective equipment in Section 8. Avoid generating dust. Prevent product from entering any drains, sewers or water sources. Refer to Section 13 for proper disposal.

Environmental precautions

Avoid release to the environment. Prevent further leakage or spillage if safe to do so.

THANDENG AND AKORAGES

Precautions for safe handling

Reduction of fumes and dusts: Keep formation of airborne dusts to a minimum. Provide appropriate

exhaust ventilation at places were dust is formed. Read and understand the manufacturer's instruction and the precautionary label on the product. See American National Standard Z49.1, "Safety In Welding, Cutting and

Allied Processes"

Do not touch live electrical parts such as the welding wire and welding Prevention of electric shock:

machine terminals. Wear insulated gloves and safety boots. If welding must be performed in damp locations or with wet clothing, on metal structures or when in cramped positions such as sitting, kneeling or lying, or if there is a high risk of unavoidable or accidental contact with workpiece, use the following equipment: Semiautomatic DC Welder, DC

Manual (Stick) Welder, or AC Welder with Reduced Voltage Control.

Prevention of fire and explosion:

Remove flammable and combustible materials and liquids.

Prevention of harm when handling welding consumables:

Handle with care to avoid stings and cuts. Hold the welding wire

manually when loosening the wire.

Conditions for safe storage, including any incompatibilities

Store welding consumables inside a room without humidity. Do not store welding consumables directly on the ground or beside a wall. Keep welding consumables away from chemical substances like acids which could cause chemical reactions. Store in accordance with local/regional/national regulations.

S PAROXITATEO ATRIOTES APERSONATERRO PER TROS

Control parameters

For substances may be included in welding fumes, gases and flux, occupational exposure values are shown in Annex. Keep exposure below exposure limits. Threshold Limit Values (TLVs) and Biological Exposure Indices (BEIs) are values published by the American Conference of Government Industrial Hygienists (ACGIH). ACGIH Statement of Positions Regarding the TLVs and BEIs states that the TLV-TWA should be used as a guide in the control of health hazards and should not be used to indicate a fine line between safe and dangerous exposures. See Section 10 for information on potential fume constituents of health interest.

Appropriate engineering controls

Ventilation: Use enough ventilation, local exhaust at the arc, or both to keep the fumes and gases

below the exposure limits in the worker's breathing zone and the general area. Keep exposure as low as possible.

Determine the composition and quantity of fumes and gases to which workers are exposed by taking an air sample from inside the welder's helmet if worn or in the worker's breathing zone. Improve ventilation if exposures are not below limits. See ANSI/AWS F1.1, F1.2, F1.3 and F1.5, available from the American Welding

Society, www.aws.org.

Individual protection measures

Eye protection: Wear helmet or use face shield with filter lens. As a rule of thumb, start with a shade

which is too dark to see the weld zone. Then go to the next lighter shade which gives sufficient view of the weld zone. Provide protective screens and flash goggles, if

necessary, to shield others.

Hand protection: Wear protective gloves. Suitable gloves can be recommended by the glove supplier.

Protective Clothing: Wear hand, head, and body protection which help to prevent injury from radiation,

sparks and electrical shock. See Z49.1. At a minimum this includes welder's gloves and a protective face shield, and may include arm protectors, aprons, hats, shoulder protection, as well as dark substantial clothing. Wear dry gloves free of holes or split seams. Train the welder not to permit electrically live parts or electrodes to contact skin or clothing or gloves if they are wet. Insulate yourself from the work piece and

ground using dry plywood, rubber mats or other dry insulation.

Respiratory protection: Keep your head out of fumes. Use enough ventilation and local exhaust to keep

fumes and gases from your breathing zone and the general area. Use respirable fume respirator or air supplied respirator when welding in confined space or where local

exhaust or ventilation does not keep exposure below exposure limits.

Ear protection: Wear earplugs or earmuffs when using engine driven arc welding machine or pulsed

arc welding machine that generates high-level

noise

Hygiene measures: Do not eat, drink or smoke when using the product. Always observe good personal

hygiene measures, such as washing after handling the material and before eating, drinking, and/or smoking. Routinely wash work clothing and protective equipment

to remove contaminants.

O BIBASICAL AND CHEMICAL PROPERTIES

Physical state: Solid

Color: Silver or Copper Odor: Odorless

Odor threshold: No further relevant information available

pH: Not applicable

Melting point/freezing point:

No further relevant information available

No further relevant information available

Flash point: Not applicable Evaporation rate: Not applicable

Flammability: No further relevant information available Upper/lower flammability or explosive limits: No further relevant information available

Vapor pressure:

Not applicable
Not applicable

Solubility(ies)

Partition coefficient (n-octanol/water):

Auto-ignition temperature:

No further relevant information available

Viscosity: Not applicable

THE STABILITIES AND RESPONDENCE

Reactivity

Non-reactive under normal conditions of storage and transport.

Chemical stability

Stable under normal conditions of storage and transport.

Possibility of hazardous reactions

Contact with acids, alkalis and oxidizing agents could cause reaction and generation of gas.

Conditions to avoid

Avoid heat or contamination of acids, alkalis and oxidizing agents.

Incompatible materials

Avoid contact with acids, alkalis and oxidizing agents.

Hazardous decomposition products

Welding fumes and gases are generated as byproducts during the welding. The composition and quantity of fumes and gases cannot be recognized simply. The composition and quantity of the fumes and gases are dependent upon the base metal being welded (included coating such as solvent, paint, plating), the welding process, welding procedure, welding parameter and electrodes used. Other conditions which also influence the quantity of the fumes and gases to which workers may be exposed include the number of welding spots, the volume of the worker area, the quality and amount of ventilation, the position of the welder's head with respect to the fume plume, as well as the presence of contaminants in the atmosphere (such as chlorinated hydrocarbon vapors from cleaning and degreasing activities.)

The fumes and gases are different in percent and form from the ingredients listed in Section 3. The fumes and gases include those originating from the volatilization, reaction, or oxidation of the materials shown in Section 3, plus those from the base metal and coating, etc., as noted above. Reasonably expected fume constituents produced during arc welding include the oxides of iron, manganese and other metals present in the welding consumable or base metal. And, it is known that these metal oxides are complex oxides, not single compounds. Hexavalent chromium compounds may be in the welding fume of consumables or base metals which contain chromium. Nickel compounds may be in the welding fume of consumables or base metals which contain Nickel. Gaseous and particulate fluoride may be in the welding fume of consumables which contain fluoride. Gaseous reaction products may include carbon monoxide and carbon dioxide. Ozone and nitrogen oxides may be formed by the radiation from the arc.

THE ROUND COMOVERS AND ENDING THE PROPERTY OF

General

Classification not possible as product. Refer to Sec.2. Inhalation of welding fumes and gases can be dangerous to your health. The composition and quantity of both are dependent upon the material being worked, the process, procedures, and consumables used. Refer to Sec.10.

Acute toxicity

Short-term (acute) overexposure to welding fumes may result in discomfort such as metal fume fever, dizziness, nausea, or dryness or irritation of nose, throat, or eyes. May aggravate pre-existing respiratory problems (e.g. asthma, emphysema).

Cr: The presence of chromium/chromate in welding fumes can cause irritation of nasal membranes and skin.

Ni: The presence of nickel compounds in fume can cause metallic taste, nausea, tightness of chest, fever.

F: Exposure to the fluoride ion in welding fumes may cause hypocalcemia-calcium deficiency in the blood that can result in muscle cramps and inflammation and necrosis of mucous membranes.

Gases: Some toxic gases associated with welding may cause pulmonary edema, asphyxiation, and death.

Chronic toxicity

Long-term (chronic) overexposure to welding fumes can lead to siderosis (iron deposits in lung), central nervous system effects, bronchitis, pneumoconiosis and other pulmonary effects. The severity of the change is proportional to the length of the exposure. The changes may be caused by non-work factors such as smoking, etc.

Ni: Long term overexposure to nickel fumes may also cause pulmonary fibrosis and edema.

Cr: Chromates may cause ulceration, perforation of the nasal septum, and severe irritation of the bronchial tubes and lungs. Liver damage have also been reported. Chromates contain the hexavalent form of chromium.

Mn: Overexposure to manganese compounds may affect the central nervous system, symptoms of which are languor, sleepiness, muscular weakness, emotional disturbances and spastic gait. The effect of manganese on the nervous system is irreversible.

Cu: Overexposure to copper fumes may lead to copper poisoning, resulting in hermolytic anemia and liver, kidney and spleen damage.

Fe: Inhalation of too much iron oxide fume over a long time can cause siderosis, sometimes called "iron pigmentation" of the lung, which can be seen on a chest x-ray but causes little or no disability. Chronic overexposure to iron (>50-100mg Fe per day) can result in pathological deposition of iron in body

tissues, symptoms of which are fibrosis of the pancreas, diabetes mellitus, and liver cirrhosis.

SiO₂: Respiratory exposure to the crystalline silica present in this welding electrode is not anticipated during normal use. Respiratory overexposure to airborne crystalline silica is known to cause silicosis, a form of disabling pulmonary fibrosis which can be progressive and may lead to death.

F: Chronic fluoride absorption can result in osseous fluorosis, increased radiographic density of the bones and mottling of the teeth.

Carcinogenicity

Welding fumes (not otherwise specified) are possibly carcinogenic to humans. Welding fumes is on the IARC lists as posing a cancer risk.

SiO₂: Crystalline silica is on the IARC (International Agency for Research on Cancer) and NTP (National Toxicology Program) lists as posing a cancer risk to humans.

Ni: Nickel and its compounds are on the IARC and NTP lists as posing respiratory cancer risk.

Cr: Hexavalent chromium and its compounds are on the IARC and NTP lists as posing a cancer risk to humans.

Arc Skin cancer has been reported.

rays:

Respiratory or Skin Sensitization

Ni: Nickel and its compounds are skin sensitizers with symptoms ranging from slight itch to severe dermatitis.

Cr: Chromates may cause allergic reactions, including skin rash. Asthma has been reported in some sensitized individuals. Skin contact may result in irritation, ulceration, sensitization, and contact dermatitis

Others

Organic polymers may be used in the manufacture of various welding consumables. Overexposure to their decomposition byproducts may result in a condition known as polymer fume fever. Polymer fume fever usually occurs within 4 to 8 hours of exposure with the presentation of flu like symptoms, including mild pulmonary irritation with or without an increase in body temperature. Signs of exposure can include an increase in white blood cell count. Resolution of symptoms typically occurs quickly, usually not lasting longer than 48 hours.

wasiakayandakayayandalorida

Ecotoxicity

Product: No further relevant information available

Persistence and degradability

Product: No further relevant information available

Bioaccumulative potential

Product: No further relevant information available

Mobility in soil

Product: No further relevant information available

BEDISBOSKIB GONSIDIBRAVITONSEESEESE

The generation of waste should be avoided or minimized whenever possible. When practical, recycle in an environmentally acceptable, regulatory compliant manner. Dispose of non-recyclable products in accordance with all applicable National, State, and Local requirements. Discharge, treatment, or disposal may be subject to National, State, or Local laws.

iee maanareitseatuonaaamient ees

UN number:
UN proper shipping name:
Not applicable
Transport hazard class(es):
Packing group:
Environmental hazards:
Not applicable

a spolicie gluddan koji a yran boj gan myblo nysyddio

Regulations of each country are applied to subustance/mixures.

IG-OPTER INFORMATION

Reference

American National Standard (ANSI) Z49.1 "Safety in Welding, Cutting, and Allied Processes"

Date of issue

2015-05-20

Disclaimer

The information given in this SDS is based on the present level of our knowledge and experience. This information is believed to be accurate as of the revision date shown above. However, no warranty, expressed or implied, is given. Because the conditions or methods of use are beyond KOBE STEEL, LTD.'s control, we assume no liability resulting from the use of this product. Regulatory requirements are subject to change and may differ between various locations. Compliance with all applicable Federal, State, Provincial, and local laws and regulations remain the responsibility of the user. If necessary, consult an industrial hygienist or other expert to understand this information and safeguard the environment and protect workers from potential hazards associated with the handling or use of this product.

Date of issue: 2015-5-20

Annex

OCCUPATIONAL EXPOSURE VALUES 1) TWA11) (mg/m3)

SUBSTANCE [CAS NO.3]	SUBSTANCE [CAS No.] 2)	LACCITATION A 4	Logar (Span 6)	1 0 71 81	1 10\
Aluminum [7429-95.5] metal and insoluble compounds, total dust Aluminum [7429-95.5] welding frome, as AI		ACGIH"TLVs"		NIOSH ⁷⁾ RELs ⁸⁾	DFG ⁹⁾ MAKs ¹⁰⁾
Abanisman 7429-90-5 metal and insoluble compounds, total diest	Aluminum [7429-90-5] metal and insoluble compounds	1 123	5 12)	5 12)	$4^{13}, [1.5^{12}]$
Alaminam (7429-90-5) welding funes, as AI	Aluminum [7429-90-5] metal and insoluble compounds, total dust		15	10	
Alaminum social [1344-28-1] Boren code [1303-86-2] Boren code [1303-86-2] Boren code [1503-86-2] Boren code [1503-	Aluminum [7429-90-5] welding fumes, as Al			f	
Alternation oxide [1344-28-1], tool digit Series oxide [1344-28-1], tool digit Series oxide [1303-8-6] Series oxid			= 12)		4 13) 5 4 6 12 7
Borno coside [1303-86-2] total dust		_	i		4 ",[1.5 "]
Boron coide 1303-862 coal dast			15		****
Barium (1440-93-3) and soluble compounds, as Ba 0.5 0.		10		10	
Barismic 17440-39-3 and soluble compounds, as Ba 0.5			15		
Bartium compounds, soluble, as Ba	Barium [7440-39-3] and soluble compounds as Ba	0.5		0.6	
Calcium arothous (1317-65-3] (NOSH: includes [471-34-1])		1	0.5		
Calcium carbonate [131-65-31] (NOSH: includes [471-34-1])					0.5 (3)
Calcium carbonate [1317-65-3], total diast		2			1 (3)
Calcium carbonate [1317-65-3], total diast	Calcium carbonate [1317-65-3] (NIOSH: includes [471-34-1])		5 12)	5 12)	
Cobalt	Calcium carbonate [1317-65-3] total dust		ł .		
Cobati 1740-48-4 and inorganic compounds, metal dust and fame, as Co					
Chromism [74404-73] (IV) inorganic compounds, as Cr		0.02			
Chromine [744047-3] (IJ) inorganic compounds, as Cr (Cr)	Cobalt [7440-48-4] and inorganic compounds, metal dust and fume, as Co		0.1	0.05	
Chromium [744047-3] (IV) inorganic compounds, as Cr	Chromium [7440-47-3] metal	0.5	ı	0.5	
Chromium [7440-47-3] (IV) compounds, as Cr (VI)	Chromium [7440-47-3] (II) inorganic compounds as Cr		ſ		
Chromium [7440-47-3] (III) inorganic compounds, as Cr		1			
Chromium [7440-47-3] (VI) inorganic compounds, water-insoluble, as Cr		t .	0.005		***
Chromium [7440-47-3] (VI) inorganic compounds, water-sinshible, as Cr (VI)		0.5	0.5	0.5	
Chromium [7440-47-3] (VI) inorganic compounds, water-sinshible, as Cr (VI)	Chromium [7440-47-3] (VI) inorganic compounds, water-soluble, as Cr	0.05		0.0002	
Chromium [7440-47-3] (VI) inorganic compounds, water-insoluble, as Cr (VI)					ļ
Chromium [7440-47-3] (VI) inorganic compounds, water-insoluble, as Cr (VI)			1 1		
Copper [7440-50-8], fune, as Cu		J	i l		
Copper [7440-50-8], dasts and mists, as Cu			0.005	***	B-1/12
Copper [7440-50-8], dusts and mists, as Cu		0.2	0.1	0.1	
Copper [7440-50-8] and its inorganic compounds	Copper [7440-50-8], dusts and mists, as Cu	ž	1 1		
Fluorides, as F) ¹		0 0 12)
Iton oxide (Fes.0.) 1309-37-1 , fame					0.01 **/
Iron oxide (Fe,Os.) [1309-37-1], furst and furne, as Fe			2.5	2.5	1 13)
Iron oxide (Fe,Qs) 1309-37-1 , furne		5 12)			
Iron oxide (Fe,O ₂) [1399-37-1], dust and fame, as Fe	Iron oxide (Fe ₂ O ₃) [1309-37-1], fume		10		
Magnesium oxide [1309-48-4], finne, total particulate	Iron oxide (Fe ₂ O ₂) [1309-37-1] dust and firme as Fe		1		
Magnesism oxide [1309-48-4], finne, total particulate 15		10.137			
Manganese [7439-96-5] and inorganic compounds, as Mn		10.07	1 7		4 107, [1.5 121]
Manganese [7439-96-5], fame, as Mn	Magnesium oxide [1309-48-4], fume, total particulate		15		
Manganese [7439-96-5], fame, as Mn	Manganese [7439-96-5] and inorganic compounds, as Mn	$[0.1^{-13}], [0.02^{-12}]$		1, [3 14)]	0.2 13) [0.02 12]
Molybdenum [7439-98-7] and soluble compounds, as Mo 0.5 13 10 10 13 13 15 15 15 15 15 15		0 1 (3) (0.02 12)		1 [3 147]	0.2 (3) [0.02 (2)]
Molybdenum [7439-98-7] and insoluble compounds, as Mo 10 115 15 15 15 15 15 15	Malyhdenum (7439.98-7) and soluble compounds as Mo	0.1 (0.02)		1, [3]	0.2 , [0.02]
Molybdenum [7439-98-7] and insoluble compounds, total dust, as Mo			- i		
Nickel [7440-02-0] soluble compounds, as Ni (ACGIH: inorganic only) Nickel [7440-02-0] soluble compounds, as Ni (ACGIH: inorganic only) Nickel [7440-02-0] soluble compounds, as Ni (ACGIH: inorganic only) Nickel [7440-02-0] soluble compounds, as Ni (ACGIH: inorganic only) Nickel [7440-02-0] compounds Silica, amorphous, fused (DFG: includes [7699-41-4]) Silica, amorphous, fused, dust Silica, amorphous, fused, total dust Silica, armorphous, fused, total dust Silica, crystalline, a-quartz, total dust Silica, crystalline, a-quartz, total dust Silicon [7440-21-3], solud dust Silicon [7440-21-3], solud dust Silicon [7440-31-5], oxide and inorganic compounds, except SnH ₄ , as Sn Tin [7440-31-5], oxide and inorganic compounds, except oxide and SnH ₄ , as Sn Tin [7440-31-5], oxide and inorganic compounds, except oxide and SnH ₄ , as Sn Tin [7440-31-5], organic compounds, as Sn Sn Tin [7440-25-7] oxide, dust, as Ta Titanium [7440-25-7] oxide, dust, as Ta Titanium dioxide [13463-67-7] Titanium dioxide [13463-67-7] total dust Silica, crystalline, a-quartz, dust Silicon [7440-33-7], soluble compounds, as W Solution [7440-67-7]		10 '3', [3 '4']			i
Nickel [7440-02-0] isoluble compounds, as Ni (ACGIH: inorganic only) Nickel [7440-02-0] isoluble compounds, as Ni (ACGIH: inorganic only) Nickel [7440-02-0] isoluble compounds, as Ni (ACGIH: inorganic only) Nickel [7440-02-0] compounds Silica, amorphous, fused (DFG: includes [7699-41-4]) Silica, amorphous, fused, total dust Silica, amorphous, fused, total dust Silica, amorphous, fused, total dust Silica, crystalline, α-quartz, total dust Silica,	Molybdenum [7439-98-7] and insoluble compounds, total dust, as Mo		15		
Nickel [7440-02-0] isoluble compounds, as Ni (ACGIH: inorganic only) Nickel [7440-02-0] isoluble compounds, as Ni (ACGIH: inorganic only) Nickel [7440-02-0] isoluble compounds, as Ni (ACGIH: inorganic only) Nickel [7440-02-0] compounds Silica, amorphous, fused (DFG: includes [7699-41-4]) Silica, amorphous, fused, total dust Silica, amorphous, fused, total dust Silica, amorphous, fused, total dust Silica, crystalline, α-quartz, total dust Silica,	Nickel [7440-02-0], elemental	1.5 (3)	1	0.015	
Nickel [7440-02-0] insoluble compounds, as Ni (ACGIH: inorganic only) Nickel [7440-02-0] compounds Nickel [7440-02-0] compounds Silica, amorphous, fused, dust Silica, crystalline, α-quartz O.025 ¹²⁾ ———————————————————————————————————	Nickel [7440-02-0] soluble compounds as Ni (ACGIH: inorganic only)				
Nickel [7440-02-0] compounds	Nickel 17440 02 01 inceluble server to an Vi (A COURT		Į.	1	[
Silica, amorphous, fissed (DFG: includes [7699-41-4])		0.2 157	1	0.015	
Silica, amorphous, fused, dust Silica, amorphous, fused, total dust Silica, amorphous, fused, total dust Silica, crystalline, α-quartz 0.025 12)				0.015	[
Silica, amorphous, fused, dust Silica, amorphous, fused, total dust Silica, amorphous, fused, total dust Silica, crystalline, α-quartz 0.025 12)	Silica, amorphous, fused (DFG: includes [7699-41-4])			0.3 (2)	
Silica, crystalline, α -quartz, dust $\begin{array}{cccccccccccccccccccccccccccccccccccc$	Silica, amorphous, fused, dust		A 12)15)		ŀ
Silica, crystalline, α-quartz 0.025 12			n 16)		
Silica, crystalline, α-quartz, total dust			B		
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$		0.025 127	1		
Silicon 7440-21-3	Silica, crystalline, α-quartz, dust		A (2)15)	0.05 (2)	
Silicon [7440-21-3] Silicon [7440-21-5] Silicon [7440-31-5]	Silica, crystalline, α-quartz, total dust	l I	B 16)		
Silicon [7440-21-3], total dust				E 12)	
Tin [7440-31-5], metal 2 2 2 2 — <td></td> <td> </td> <td>_</td> <td>,</td> <td></td>			_	,	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$				10	
Tin [7440-31-5], oxide, as Sn Tin [7440-31-5], oxide and inorganic compounds, except SnH4, as Sn Tin [7440-31-5], oxide and inorganic compounds, except oxide and SnH4, as Sn Tin [7440-31-5], organic compounds, as Sn Tin [7440-31-7], organic compounds, as Zn Tin [7440-31-7], organic		2	2	2	
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$		2			
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	Tin [7440-31-5], oxide and inorganic compounds, except SnH., as Sn				1
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	Tin [7440-31-5], oxide and inorganic commounds, except oxide and Coll	~	1	-	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	Co		2		
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$			ļ		1
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$		$0.1, [0.2^{-14}]$	0.1	0.1	0.1 (3)
Tantalum [7440-25-7] oxide, dust, as Ta	Tantalum [7440-25-7], metal			5, [10 147]	4 13) [1.5 12)]
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$					1
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$		10		2,110	
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	· · ·				
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$			15		
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$, , , , , , , , , , , , , , , , , , ,				
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	Ferrovanadium [12604-58-9] dust		f I	1 [3 14)?	أ
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$		5 F10 14h		5 510 143	
Zinc oxide [1314-13-2], total dust — 15 — — Zinc oxide [1314-13-2], dust only — 5 — — Zinc oxide [1314-13-2], fume — 5 5, [10 145] 0.1 125, [2 135] Zirconium [7440-67-7] 5, [10 145] — — Zirconium [7440-67-7] insoluble compounds — 5, [10 145] — Zirconium [7440-67-7] insoluble compounds — 5, [10 145] [130	,,	2, [10], [1	1	5,[10]	
Zinc oxide [1314-13-2], total dust — 15 — — Zinc oxide [1314-13-2], dust only — 5 — — Zinc oxide [1314-13-2], fume — 5 5, [10 145] 0.1 125, [2 135] Zirconium [7440-67-7] 5, [10 145] — — Zirconium [7440-67-7] insoluble compounds — 5, [10 145] — Zirconium [7440-67-7] insoluble compounds — 5, [10 145] [130		1, [3 *)		1, [3 14)]	
Zinc oxide [1314-13-2], total dust — 15 — — Zinc oxide [1314-13-2], dust only — 5 — — Zinc oxide [1314-13-2], fume — 5 5, [10 145] 0.1 125, [2 135] Zirconium [7440-67-7] 5, [10 145] — — Zirconium [7440-67-7] insoluble compounds — 5, [10 145] — Zirconium [7440-67-7] insoluble compounds — 5, [10 145] [130	Zinc oxide [1314-13-2]	2 12), [10 12)14)]	5 12)		0.1^{12} , 12^{13})
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	Zinc oxide [1314-13-2], total dust	' *			··· ',"]
Zinc oxide [1314-13-2], fume 5 5, [10 14] 0.1 12 , [2 13] Zirconium [7440-67-7] 5, [10 14] Zirconium [7440-67-7] compounds, as Zr 5, [10 14] 5 5, [10 14] Zirconium [7440-67-7] insoluble compounds 5, [10 14] [13)		_ [
Zirconium [7440-67-7] 5, $[10^{18}]$ — — — — — — — — Zirconium [7440-67-7] insoluble compounds — — 5, $[10^{14}]$ 5 5, $[10^{14}]$ — — 5, $[10^{14}]$ [13) — — — 5, $[10^{14}]$ [13) —					
Zirconium [7440-67-7] 5, [10 14] — — — — — — — — — — 5, [10 14]] — — — 5, [10 14]] [13) — — 5, [10 14]] [13) — — 5, [10 14]] [13) — — — 5, [10 14]] [13) —		1	5	5, [10 14]	$0.1^{-123}, [2^{-133}]$
Zirconium [7440-67-7] compounds, as Zr					
Zirconium [7440-67-7] insoluble compounds 5, 110 147 1 13)	Zirconium [7440-67-7] compounds, as Zr			5. [10 14]1	{
Zirconium [7440-67-7] soluble compounds - 5, [10 14] - 5, [10 14]		-71 1	-	5 [10 14]	r 13)
2.1 Commun [1770-07-7] Soutole Compounds - 5, [10 197] 5, [10 197]				3, [10]	3
	LEN COMMUNE (TTO-O1-1) SOMOTE COMPOUNDS			5, [10 '*']	

Date of issue: 2015-5-20

(Continued) OCCUPATIONAL EXPOSURE VALUES 1) TWAII) (ppm)

SUBSTANCE [CAS No.12)	ACGIH ³⁾ TLVs ⁴⁾		MIOSH7) DEL (8)	DEC9) MAY (0)
Phenol [108-95-2]	5	5	5	DIG MAKS
Carbon monoxide [630-08-0]	25	50	35	30
Carbon dioxide [124-38-9]	5000, [30000 14), 13)]	5000	5000, [30000 143]	
Phosgene [75-44-5]	0.1	0.1	0.1	0.1
Hydrogen fluoride [7664-39-3] as F	0.5, [2 14)]	3	3	1
Nitric oxide [10102-43-9]	25	25	25	
Nitrogen dioxide [10102-44-0]	0.2		1 (4)	0,5
Ozone [10028-15-6]		0.1	0.1 (4)	<u>, , , , , , , , , , , , , , , , , , , </u>
Heavy work	0.05		0,1	
Moderate work	0.08			
Light work	0.1			
Light, moderate, or heavy workload (≤2 hours)	0.2			~~~
Phosphine [7803-51-2]	0.3, [1 14]	0.3	0.3, [1 14)]	0.1

- 2014 Guide to Occupational Exposure Values, ACGIH
- Chemical Abstract Service Registry Number
- American Conference of Governmental Industrial Hygienists ACGIH Threshold Limit Values
- 3) 4) 5) U.S. Occupational Safety and Health Administration
- 6) OSHA Permissible Exposure Limits
- U.S. National Institute for Occupational Safety and Health
- NIOSH Recommended Exposure Limits Deautsche Forschungsgemeinschaft 8)
- DFG Maximum Concentrations at the Workplace 10)
- Time-weighted average exposure concentration for a conventional 8-hour (TLV, PEL) or up to a 10-hour (REL) workday and a 40-hour workweek
- Measured as respirable fraction of the aerosol.
 Measured as inhalable fraction of the aerosol.
- The concentration that shall not be exceeded during any part of the working exposure
- or 10mg/m³ 250mppcf %SiO²+2
- %SiO²+5 16) 30mg/m³ %SiO²+2



SAFETY DATA SHEET

SECTION 1: PRODUCT AND COMPANY IDENTIFICATION

Manufacturer/Supplier Name: Sandvik Wire and Heating Technologies

Address: P.O. Box 1220, Scranton, PA 18501-1220

Phone Number: (570) 585-7500

Trade Name: SANDVIK

Classification: AWS A5.9/ASME SFA 5.9, ASME SFA 5.9 Section III, MIL-E-19333, ABS, CWB-AWS A5.9

Corrosion Resisting Chromium and Chromium Nickel Steel Bare Wire and Strip Welding Electrodes

and Welding Rods.

Product Type: Cr-Ni Bare Wire and Strip Electrodes and Rod for manual, semi-automatic, and automatic

welding processes.

Product Identifiers: 18Cb, 307,308/308L, 308LSi, 308/308H, 347, 347Si, 347L, 316/316L, 316LSi, 316/316H, 317L, 309L, 309LCb, 309LHF, 309, 309LSi, 309MoL, 310, 310H, 312, 320, 330, 409Cb, 410, 410NiMo, 420, 430, 630,383,385, 20.25.5LCu, 21.11.LNb, 21.13.3.L, 25.22.2.LMn, 27.31.4.LCu, 22.12.HT, 2209, 25.20.L, 25.10.4.L, 16.13CMnW, 442, 439Ti, 439, 19.TiCb, 430LCb, 430LCbTi, Sandvik Sanweld® AXT

SECTION 2: HAZARDS IDENTIFICATION

Chromium-Nickel bare wire and electrodes and strip are welding consumables which are either solid wire or strip.

EMERGENCY OVERVIEW

Effects of Over-exposure:

Electric arc welding may create one or more of the following health hazards:

FUMES AND GASES can be dangerous to your health.

SHORT-TERM (acute) OVEREXPOSURE to welding fumes may result in discomfort, such as dizziness, nausea, or dryness or irritation of nose, throat, or eyes.

LONG-TERM (chronic) OVEREXPOSURE to welding fumes can lead to siderosis (iron deposits in lungs), central nervous system, liver or kidney damage, skin and respiratory sensitization (allergic reaction), and is believed by some investigators to affect pulmonary function.

PRIMARY ROUTE OF ENTRY is the respiratory system.

MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE: Pre-existing eye, respiratory or allergic conditions.

ARC RAYS can injure eyes and burn skin.

ELECTRIC SHOCK can kill,

CARCINOGENICITY:

Certain hexavalent chromium compounds, nickel metal and compounds and respirable crystalline silica are listed in the National Toxicology Program (NTP) Annual Report on Carcinogens, found to be a potential carcinogen in the International Agency for Research on Cancer (IARC) Monographs, or listed by OSHA/ACGIH as potential carcinogens.

SECTION 3: COMPOSITION/INFORMATION ON INGREDIENTS

The following is composition information of the product as manufactured.

Hazardous Ingredient	CAS No.	WT %
Chromium (Cr)	7440-47-3	1-30
Copper (Cu)	7440-50-8	0-4
Iron (Fe)	7439-89-6	Bal.
Manganese (Mn)	7439-96-5	1-7
Molybdenum (Mo) 1)	7439-98-7	1-5
Nickel (Ni)	7440-02-0	1-35
Niobium (Nb) 2)	7440-03-1	0.5-1
Silicon (Si)	7440-21-3	0.4-2



The following are typical constituents of welding fumes and gases. When the electrode is consumed, the fume and gas decomposition products generated are different in percent and form than ingredients listed above. Decomposition products of normal operation include those originating from the volatilization reaction, or oxidation of the materials shown above, plus those from the base metal and coating, etc. which may include paint, plating, galvanizing, or phosphate coatings on steels which would produce phosphine gas and other contaminants in the atmosphere (such as chlorinated hydrocarbon vapors from cleaning and degreasing activities which may be decomposed by the arc into toxic gases such as phospene).

Fume Constituent (Gases)	CAS No.	Fume Constituents (Solids)	CAS No.
Dinitrogen Tetroxide (N ₂ O ₄)	10544-72-6	Chromates (CrO ₃)	1333-82-0
Nitric Oxide (NO)	10102-43-9	Copper Oxide (CuO)	1344-70-3
Nitrogen Dioxide (NO ₂)	10102-44-0	Manganese Oxide (MnO)	11129-60-5
Ozone (O ₃)	10028-15-6	Nickel Oxide (NiO)	1314-06-3
Phosgene (COCl ₂) *	75-44-5	Iron Oxide (Fè ₂ O ₃)	1309-37-1
Phosphine (PH ₃) **	7803-51-2	Molybdenum Trioxide (MoO ₃) 1)	1313-27-5
		Niobium Oxide (NbO) 2)	12034-57-0
		Silica (SiO ₂) (quartz)	14808-60-7

^{*} May result from contact with chlorinated hydrocarbon vapors.

Refer to Section 8 for occupational exposure limits.

SECTION 4: FIRST AID MEASURES

Eye: If eye irritation occurs, flush eyes immediately with water while holding open eyelids. Get medical attention if irritation persists.

Skin: None normally needed. Get immediate medical attention for treatment of burns.

Inhalation: Remove victim to fresh air. Give artificial respiration if needed. If breathing is difficult, oxygen should be administered by qualified personnel. Get immediate medical attention.

SECTION 5: FIRE FIGHTING MEASURES

(Nonflammable) – Welding arc and sparks can ignite combustibles and flammables. Refer to American National Z49.1 for fire prevention during the use of welding and allied procedures.

SECTION 6: ACCIDENTAL RELEASE MEASURES

Pick up and return to container for use.

SECTION 7: HANDLING AND STORAGE

Avoid breathing welding fumes. Keep your head out of the fumes. Use with enough ventilation or exhaust at the arc, or both, to keep fumes and gases below the occupational exposure limits in your breathing zone and the general area. Use air sampling to determine the need for corrective action. (Refer to Section 10 for additional information)

Work in a confined space only if it is well ventilated, or while wearing an air-supplied respirator. Fumes from welding and oxygen depletion can alter the air quality causing injury or death.

Take appropriate precautions to prevent fires and explosion.

Read and understand the manufacturer's instructions and the precautionary label on the product. See American National Standard Z49.1, Safety in Welding and Cutting, published by the American Welding Society, P.O. Box 351040, Miami, FL 33135; and OSHA Publication 2206 (29CRF 1910), U.S. Government Printing Office, Washington, DC 20402, for more information. Assure compliance with the OSHA Standard on Chromium (VI), 29CFR 1910.1026.

^{**} May result from welding on phosphate coated steels.

¹⁾ Only in Molybdenum-alloyed grades.

²⁾ Only in Niobium-alloyed grades.

Revision 11

Issue Date - July, 2013



Storage: Store in a clean dry area.

SECTION 8: EXPOSURE CONTROLS/PERSONAL PROTECTION

See Appendix A for occupational exposure limits for Canadian Provinces

The following are the occupational exposure limits for the components of the product as manufactured.

<u>Ingredient</u>	OSHA PEL	ACGIH TLV	ACGIH STEL
Chromium (Cr) (as metal)	1 mg/m3 TWA	0.5 mg/m3 TWA	_
Copper (Cu) (as dust and mists)	1 mg/m3 TWA	1 mg/m3 TWA	-
fron (Fe) (as Iron oxide)	10 mg/m3 TWA (as fume)	5 mg/m3 TWA (respirable)	
Manganese (Mn)	5 mg/m3 Ceiling Limit	0.02 mg/m3 TWA (respirable fraction) 0.1 mg/m3 TWA (inhalable)	-
Molybdenum (Mo) 1)	15 mg/m3 TWA (total dust)	3 mg/m3 TWA (respirable fraction) 10 mg/m3 TWA (inhalable)	-
Nickel (Ni) (elemental)	1 mg/m3 TWA	1.5 mg/m3 TWA (inhalable)	
Niobium (Nb) 2)	None Established	None Established	-
Silicon (Si)	5 mg/m3 TWA (respirable fraction) 15 mg/m3 TWA (total dust)	None Established	<u>-</u>

The following are the occupational exposure limits for the typical decomposition products.

GASES			
Fume Constituent	OSHA PEL	ACGIH TLV	ACGIH STEL
Dinitrogen Tetroxide (N ₂ O ₄)	None Established	None Established	- MOONTOTEL
Nitric Oxide (NO)	25 ppm TWA	25 ppm TWA	
Nitrogen Dioxide (NO ₂)	5 ppm Ceiling	3 ppm TWA	
Ozone (O ₃)	0.1 ppm TWA	0.1 ppm ***	-
Phosgene (COCl ₂) *	0.1 ppm TWA	0.1 ppm TWA	
Phosphine (PH ₃) **	0.3 ppm TWA	0.3 ppm TWA	1 ppm

SOLIDS			
Fume Constituents	OSHA PEL	ACGIH TLV	ACGIH STEL
Chromates (CrO₃) (CrVI)	0.005 mg/m3 TWA (as CrVI) 0.0025 action level	0.05 mg/m3 TWA water soluble(as Cr) 0.01 mg/m3 TWA certain water insoluble (as Cr)	-
Chromium (III) Compounds	0.5 mg/m3 TWA (as Cr)	0.5 mg/m3 TWA (as Cr)	
Copper Oxide (CuO) (as copper fume)			-
Iron Oxide	10 mg/m3 TWA (as fume)	5 mg/m3 TWA (respirable)	
Manganese Oxide (MnO) (as Mn)	5 mg/m3 Ceiling (fume)	0.2 mg/m3 TWA (fume)	-
Molybdenum Trioxide (MoO ₃) ¹⁾ (as Mo)	15 m/m3 TWA (total dust)	3 mg/m3 TWA (respirable fraction) 10 mg/m3 TWA (inhalable)	-
Nickel Oxide (NiO) (as Ni)	1 mg/m3 TWA	0.2 mg/m3 TWA (inhalable)	
Niobium Oxide (NbO) 2)	None Established	None Established	-
Silica (SiO₂) (quartz)	$ \begin{array}{c c} \underline{10} & \text{(respirable} \\ \text{\%SiO}_2 + 2 & \text{fraction) TWA} \\ \underline{30} & \text{(total dust)} \\ \text{\%SiO}_2 + 2 & \text{TWA} \\ \end{array} $	0.025 mg/m3 TWA (respirable fraction)	_

¹⁾ Only in Molybdenum-alloyed grades.

²⁾ Only in Niobium-alloyed grades.



Definitions:

Permissible Exposure Limit (PEL) OSHA (29CFR 1910) – An exposure limit that is published and enforced by OSHA as a legal standard.

Threshold Limit Value (TLV) – American Conference of Governmental Industrial Hygienists – Time weighted average (TWA) concentration for a normal 8-hour work day and a 40-hour work week to which nearly all workers may be repeatedly exposed, day after day, without adverse effect.

Short Term Exposure Limit (STEL) OSHA (29CFR 1910) – A 15-minute time weighted average exposure which should not be exceeded at any time during a work day.

Ceiling Limit - The concentration that should not be exceeded during any part of the working exposure.

- * May result from contact with chlorinated hydrocarbon vapors.
- ** May result from welding on phosphate coated steels.
- *** For light work: 0.1ppm; for moderate work: 0.08ppm; and for heavy work: 0.05ppm of O₃.

Ventilation: Use enough ventilation, local exhaust at the arc, or both, to keep the fumes and gases below TLV/PEL in the workers' breathing zone and the general area. Train each welder to keep his/her head out of the fumes. Refer to ANSI Z49.1 and Section 10 for additional information.

Respiratory Protection: Use respirable fume respirator or air-supplied respirator when welding in confined area, or where local exhaust or ventilation does not keep exposure below TLV/PEL. Respirator selection and use should be based on contaminant type, form and concentration. Follow OSHA 1910.134, OSHA 1910.1026, ANSI Z88.2 and good Industrial Hygiene practice.

Protective Clothing: Wear head, hand, and body protection to help prevent injury from radiation, sparks, and electric shock. See ANSI Z49.1 and OSHA 1910.1026. At a minimum, this includes welder's gloves and a protective face shield, and may include arm protectors, aprons, hats, shoulder protection, and dark substantial clothing. Train each welder not to touch live electrical parts, and to insulate his/her person from work and ground.

Eye Protection: Wear helmet or use face shield with filter lens. Lens filter should be as dark as possible without obstructing view of the weld zone. Provide protective screens and flash goggles, if necessary, to shield others.

SECTION 9: PHYSICAL AND CHEMICAL PROPERTIES

Chromium-Nickel bare wire and electrodes and strip are welding consumables which are either solid wire or strip.

SECTION 10: STABILITY AND REACTIVITY

Stability: Stable under normal conditions of storage or use.

Incompatibility/Conditions to Avoid: None known. Welding arc and sparks can ignite combustibles and flammables. Refer to American National Z49.1 for fire prevention during the use of welding and allied procedures.

Hazardous Decomposition Product

Welding fumes and gases cannot be classified simply. The composition and quantity of both are dependent upon the metal being welded, and the process, procedures, and electrodes used. Other conditions which also influence the composition and quantity of the fumes and gases to which workers may be exposed include: coatings on the metal being welded (such as paint, plating, galvanizing, or phosphate coatings on steels which would produce phosphine gas), the number of welders and the volume of the work area, the quality and amount of ventilation, the position of the welder's head with respect to the fume plume, as well as the presence of contaminants in the atmosphere (such as chlorinated hydrocarbon vapors from cleaning and degreasing activities which may be decomposed by the arc into toxic gases such as phosgene).

When the electrode is consumed, the fume and gas decomposition products generated are different in percent and form than ingredients in the manufactured product. Typical decomposition is also listed in Section 3. Decomposition products of normal operation include those originating from the volatilization reaction, or oxidation of the materials shown in Section 3, plus those from the base metal and coating, etc., as noted above.



One recommended way to determine the composition and quantity of fumes and gases to which workers are exposed is to take an air sample inside the welder's helmet, if worn, or in the worker's breathing zone. See ANSI/AWS F1.1, available from the American Welding Society, P.O. Box 351040, Miami, FL 33135.

SECTION 11: TOXICOLOGICAL INFORMATION

No acute toxicity data is available; however, these products are not expected to be acutely toxic. See Section 2 for information on human health effects.

SECTION 12: ECOLOGICAL INFORMATION

No specific data is available. These products are not expected to present an environmental hazard.

SECTION 13: DISPOSAL INFORMATION

WASTE DISPOSAL METHOD: Prevent waste from contaminating the surrounding environment. Discard any product, residue, disposable container, or liner in an environmentally accepted manner, in full compliance with federal, state, and local regulations.

SECTION 14: TRANSPORT INFORMATION

These products are not regulated for transportation under DOT, IATA or IMDG.

SECTION 15: REGULATORY INFORMATION

CERCLA 103 Reportable Quantity: These products are not subject to CERCLA reporting requirement.

SARA TITLE III:

Hazard Category for Section 311/312: Acute Health, Chronic Health

Section 313 (40CFR 372) Toxic Chemicals: This product contains the following chemicals subject to SARA Title III Section 313 Reporting requirements:

Chromium*	7440-47-3	1-30%
Copper*	7440-50-8	0-4%
Manganese*	7440-96-5	1-5%
Nickel*	7440-02-0	1-35%

^{*} This includes all compounds of these elements.

Section 302 Extremely Hazardous Substances (TPQ): None

EPA Toxic Substances Control Act (TSCA) Status: All of the components of this product are listed on the TSCA inventory.

California Proposition 65: This product contains chromium and nickel, which are known to the State of California to cause cancer.

Canadian Environmental Protection Act: All of the ingredients are listed on the Canadian Domestic Substances List.

Canadian WHMIS Classification: Class D-2-A (Very Toxic Material causing other toxic effects)

This SDS has been prepared according to the criteria of the Controlled Products Regulation (CPR) and the MSDS contains all of the information required by the CPR.



EU RoHS: Finished welds using Sandvik welding consumables are RoHS compliant. Sandvik Stainless Steel Welding Products contain Chromium. When welded Sandvik Stainless Steel Welding Products will produce Cr VI (hexavalent chrome), however, the weld deposit does not contain Cr VI as it will all be in the zero valent state or as Cr III as an oxide. Finished products manufactured using Sandvik Stainless Steel Welding Products will not contain Cr VI.

SECTION 16: OTHER INFORMATION

HMIS Ratings:	Health – 1*	Flammability - 0	Instability - 0
NFPA Ratings:	Health - 1	Flammability - 0	Physical Hazard - 0

SDS Updated July 2013 Comprehensive Review. Updated exposure limits.

DISCLAIMER: This product is intended for use only by qualified individuals experienced and trained in welding safety. Conditions of use and suitability of the product for particular uses are beyond our control, and while the information herein is given in good faith, SANDVIK MAKES NO WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE. Nor does Sandvik assume any liability arising out of use of the product described herein. In no event shall Sandvik be liable for any special, incidental, or consequential damages in connection with this SDS.

Appendix A

Occupational Exposure Limits for Canadian Provinces

The following are the occupational exposure limits for the components of the product as manufactured.

<u>Ingredient</u>	CAS	Ontario	Quebec	British Columbia
Chromium (Cr) (as chromium metal)	7440-47-3	0.5 mg/m3 TWA	0.5 mg/m3 TWA	0.5 mg/m3 TWA
Copper (Cu) (as copper dust and mist)	7440-50-8	1 mg/m3 TWA	1 mg/m3 TWA	1 mg/m3 TWA
Iron (Fe) (as iron oxide)	7439-89-6	5 mg/m3 TWA (respirable dust)	5 mg/m3 TWA	5 mg/m3 TWA
Manganese (Mn) (as Mn and inorganic compounds)	7439-96-5	0.2 mg/m3 TWA	5 mg/m3 TWA	0.2 mg/m3 TWA
Molybdenum (Mo) 1) (as Mo and insoluble compounds)	7439-98-7	3 mg/m3 TWA respirable 10 mg/m3 TWA inhalable	10 mg/m3 TWA (as insoluble compounds)	3 mg/m3 TWA respirable 10 mg/m3 TWA inhalable
Nickel (Ni)	7440-02-0	1 mg/m3 TWA inhalable (metal) 0.2 mg/m3 TWA inhalable (insoluble)	1.0 mg/m3 TWA (as metal and insoluble compounds)	0.05 mg/m3 TWA (as metal and inorganic compounds)
Niobium (Nb) 2)	7440-03-1	None Established	None Established	None Established
Silicon (Si)	7440-21-3	10 mg/m3 TWA total dust	10 mg/m3 TWA total dust	10 mg/m3 TWA total dust (as PNOC)

The following are the occupational exposure limits for the typical decomposition products.

^{*} indicates the potential for chronic health effects.



GASES			
Fume Constituent	Ontario	Quebec	British Columbia
Dinitrogen Tetroxide (N ₂ O ₄)	None Established	None Established	None Established
Nitric Oxide (NO)	25 ppm TWA	25 ppm TWA	25 ppm TWA
Nítrogen Dioxide (NO ₂)	3 ppm TWA 5 ppm STEL	3 ppm TWA	1 ppm Ceiling
Ozone (O ₃)	0.1 ppm TWA 0.3 ppm STEL	0.1 ppm Ceiling	0.1 ppm TWA***
Phosgene (COCI ₂) *	0.1 ppm TWA	0.1 ppm TWA	0.1 ppm TWA
Phosphine (PH ₃) **	0.3 ppm TWA 1 ppm STEL	0.3 ppm TWA 1 ppm STEL	0.3 ppm TWA 1 ppm STEL

SOLIDS			
Fume Constituent <u>t</u>	Ontario	Quebec	British Columbia
Chromates (CrO₃) (CrVI)	0.01 mg/m3 TWA (as insoluble compounds) 0.05 mg/m3 TWA (as hexavalent chromium comp)	0.01 mg/m3 TWA (as water insoluble comp) 0.05 mg/m3 TWA (as water soluble comp)	0.01 mg/m3 TWA (insoluble) 0.025 mg/m3 TWA (water soluble) 0.1 mg/m3 Ceiling
Chromium (III) Compounds	0.5 mg/m3 TWA	0.5 mg/m3 TWA	0.5 mg/m3 TWA
Copper Oxide (CuO) (as copper fume)	0.2 mg/m3 TWA	0.2 mg/m3 TWA	0.2 mg/m3 TWA
Iron Oxide (as fume)	5 mg/m3 TWA respirable	5 mg/m3 TWA	5 mg/m3 TWA 10 mg/m3 STEL
Manganese oxide (MnO) (as Mn inorganic compounds)	0.2 mg/m3 TWA	5 mg/m3 TWA	0.2 mg/m3 TVVA
Molybdenum Trioxide (MoO3) ¹⁾ (as insoluble compounds)	3 mg/m3 TWA (respirable) 10 mg/m3 TWA (inhalable)	3 mg/m3 TWA (respirable)	3 mg/m3 TWA (as (respirable) 10 mg/m3 TWA (inhalable)
Nickel Oxide (NiO) (as nickel soluble compounds)	0.1 mg/m3 TWA (inhalable)	0.1 mg/m3 TWA	0.05 mg/m3 TWA
Niobium Oxide (NbO) 2)	None Established	None Established	None Established
Silica (SiO ₂) (quartz)	0.1 mg/m3 TWA	0.1 mg/m3 TWA (respirable)	0.025 mg/m3 TWA

The following are the occupational exposure limits for the components of the product as manufactured.

Ingredient	CAS	Prince Edward Island	<u>Saskatchewan</u>	Alberta
		Newfoundland and Labrador		T T T T T T T T T T T T T T T T T T T
Chromium (Cr)	7440-47-3	0.5 mg/m3 TWA	0.5 mg/m3 TWA 1.5 mg/m3 STEL	0.5 mg/m3 TWA
Copper (Cu) (as copper dust and mist)	7440-50-8	1 mg/m3 TWA	1 mg/m3 TWA	1 mg/m3 TWA
Iron (Fe) (as iron oxide)	7439-89-6	5 mg/m3 TWA (respirable)	5 mg/m3 TWA 10 mg/m3 STEL (dust and fume)	5 mg/m3 TWA (respirable)
Manganese (Mn) (as Mn metal and inorganic compounds)	7439-96-5	0.2 mg/m3 TWA	0.2 mg/m3 TWA 0.6 mg/m3 STEL	0.2 mg/m3 TWA
Molybdenum (Mo) 1) as Mo and insoluble compounds)	7439-98-7	3 mg/m3 TWA (respirable fraction) 10 mg/m3 TWA inhalable)	3 mg/m3 TWA (respirable) 6 mg/m3 STEL 10 mg/m3 TWA (inhalable) 20 mg/m3 STEL	3 mg/m3 TWA (respirable) 10 mg/m3 TWA (total dust)



Ingredient	CAS	Prince Edward Island	<u>Saskatchewan</u>	Alberta
		Newfoundland and Labrador		
Nickel (Ni) (as nickel metal)	7440-02-0	1.5 mg/m3 TWA (inhalable)	1.5 mg/m3 TWA (inhalable fraction) 3 mg/m3 STEL	1.5 mg/m3 TWA
Niobium (Nb) 2)	7440-03-1	None Established	None Established	None Established
Silicon (Si)	7440-21-3	None Established	10 mg/m3 TWA 20 mg/m3 STEL	3 mg/m3 TWA (respirable) 10 mg/m3 TWA (total dust) (as PNOC)

The following are the occupational exposure limits for the typical decomposition products.

GASES			
Fume Constituent	Prince Edward Island	<u>Saskatchewan</u>	Alberta
	Newfoundland and Labrador		
Dinitrogen Tetroxide (N ₂ O ₄)	None Established	None Established	None Established
Nitric Oxide (NO)	25 ppm TWA	25 ppm TWA 38 ppm STEL	25 ppm TWA
Nitrogen Dioxide (NO ₂)	3 ppm TWA 5 ppm STEL	3 ppm TWA 5 ppm STEL	3 ppm TWA 5 ppm STEL
Ozone (O ₃)	0.1 ppm TWA***	0.05 ppm TWA 0.15 ppm STEL	0.1 ppm TWA 0.3 ppm STEL
Phosgene (COCl ₂) *	0.1 ppm TWA	0.1 ppm TWA 0.3 ppm STEL	0.1 ppm TWA
Phosphine (PH ₃) **	0.3 ppm TWA 1 ppm STEL	0.3 ppm TWA 1 ppm STEL	0.3 ppm TWA 1 ppm STEL

SOLIDS			
<u>Fume Constituent</u>	Prince Edward Island	Saskatchewan	<u>Alberta</u>
	Newfoundland and Labrador		
Chromates (CrO ₃) (CrVI)	0.05 mg/m3 TWA (water soluble comp) 0.01 mg/m3 TWA (certain water insoluble comp)	0.05 mg/m3 TWA, 0.15 mg/m3 STEL (soluble) 0.01 mg/m3 TWA 0.03 mg/m3 STEL (insoluble)	0.05 mg/m3 TWA (soluble comp) 0.01 mg/m3 TWA (as insoluble compounds)
Chromium (III) Compounds	0.5 mg/m3 TWA	0.5 mg/m3 TWA 1.5 mg/m3 STEL	0.5 mg/m3 TWA
Copper Oxide (CuO) (as copper fume)	0.2 mg/m3 TWA	0.3 mg/m3 TWA 0.6 mg/m3 STEL	0.2 mg/m3 TWA
Iron Oxide	5 mg/m3 TWA (respirable)	5 mg/m3 TWA 10 mg/m3 STEL (as fume)	5 mg/m3 TWA (respirable)
Manganese Oxide (MnO)	0.2 mg/m3 TWA (as fume)	0.2 mg/m3 TWA 0.6 mg/m3 STEL (as inorganic compound)	0.2 mg/m3 TWA (inorganic compound)
Molybdenum Trioxide (MoO ₃) (as molybdenum insoluble compounds)	3 mg/m3 TWA (respirable fraction) 10 mg/m3 TWA (inhalable)	3 mg/m3 TWA, 6 mg/m3 STEL (respirable) 10 mg/m3 TWA , 20 mg/m3 STEL (total dust)	3 mg/m3 TWA respirable 10 mg/m3 TWA (total dust)
Nickel Oxide (NiO) (as nickel soluble compounds)	0.1 mg/m3 TWA	0.1 mg/m3 TWA, 0.3 mg/m3 STEL	0.1 mg/m3 (soluble)



SOLIDS			
Fume Constituent	Prince Edward Island	<u>Saskatchewan</u>	<u>Alberta</u>
	Newfoundland and Labrador		
Niobium Oxide (NbO) 2)	None Established	None Established	None Established
Silica (SiO ₂) (quartz)	0.025 mg/m3 TWA	0.005 mg/m3 TWA	0.025 mg/m3 TWA (respirable)

The following are the occupational exposure limits for the components of the product as manufactured.

<u>Ingredient</u>	CAS	Nunavut	Yukon	Nova Scotia
		Northwest Territories		New Brunswick Manitoba
Chromium (Cr) (as chromium metal)	7440-47-3	0.5 mg/m3 TWA (as Cr metal) 1.5 mg/m3 STEL	0.1 mg/m3 TWA (as Cr metal) 3 mg/m3 STEL	0.5 mg/m3 TWA
Copper (Cu) (as copper dust and mist)	7440-50-8	1 mg/m3 TWA 2 mg/m3 STEL	1 mg/m3 TWA 2 mg/m3 STEL	1 mg/m3 TWA
Iron (Fe) (as iron oxide)	7439-89-6	5 mg/m3 TWA (as fume) 10 mg/m3 STEL	5 mg/m3 TWA (as fume) 10 mg/m3 STEL	5 mg/m3 TWA (respirable dust)
Manganese (Mn) (as Mn and inorganic compounds)	7439-96-5	5 mg/m3 Ceiling	5mg/m3 TWA	0.2 mg/m3 TWA
Molybdenum (Mo) 1) (as Mo and insoluble compounds)	7439-98-7	10 mg/m3 TWA 20 mg/m3 STEL	10 mg/m3 TWA 20 mg/m3 STEL	3 mg/m3 TWA respirable 10 mg/m3 TWA inhalable
Nickel (Ni)	7440-02-0	1 mg/m3 TWA 2 mg/m3 STEL	1 mg/m3 TWA 3 mg/m3 STEL	1.5 mg/m3 TWA inhalable
Niobium (Nb) 2)	7440-03-1	None Established	None Established	None Established
Silicon (Si)	7440-21-3	5 mg/m3 TWA (respirable) 10 mg/m3 TWA (total dust)	10 mg/m3 TWA 20 mg/m3 STEL	None Established

The following are the occupational exposure limits for the typical decomposition products.

GASES			
Fume Constituent	<u>Nunavut</u>	Yukon	Nova Scotia
	Northwest Territories		New Brunswick
···			Manitoba
Dinitrogen Tetroxide (N ₂ O ₄)	None Established	None Established	None Established
Nitric Oxide (NO)	25 ppm TWA 35 ppm STEL	25 ppm TWA 35 ppm STEL	25 ppm TWA
Nitrogen Dioxide (NO ₂)	3 ppm TWA 5 ppm STEL	5 ppm TWA	3 ppm TWA 5 ppm STEL
Ozone (O ₃)	0.1 ppm TWA 0.3 ppm STEL	0.1 ppm TWA 0.3 ppm STEL	0.1 ppm TWA ***
Phosgene (COCl ₂) *	0.1 ppm TWA 0.3 ppm STEL	0.1 ppm TWA 0.3 ppm STEL	0.1 ppm TWA



GASES			
Fume Constituent	<u>Nunavut</u>	<u>Yukon</u>	Nova Scotia
	Northwest Territories		New Brunswick
			<u>Manitoba</u>
Phosphine (PH ₃) **	0.3 ppm TWA 1 ppm STEL	0.3 ppm TWA 1 ppm STEL	0.3 ppm TWA 1 ppm STEL

SOLIDS			
Fume Constituent	Nunavut	Yukon	Nova Scotia
	Northwest Territories		New Brunswick
			Manitoba
Chromates (CrO₃) (CrVI)	0.05 mg/m3 TWA 0.15 mg/m3 STEL (soluble or insoluble compounds)	0.1 mg/m3 TWA 0.1 mg/m3 STEL (as chromates))	0.05 mg/m3 TWA (as water soluble comp) 0.01 mg/m3 TWA (ascertain water insoluble
Chromium (III) Compounds	0.5 mg/m3 TWA, 1.5 mg/m3 STEL	0.15 mg/m3 TWA 0.15 mg/m3 STEL	0.5 mg/m3 TWA
Copper Oxide (CuO) (as copper fume)	0.2 mg/m3 TWA 0.6 mg/m3 STEL	0.2 mg/m3 TWA 0.2 mg/m3 STEL	0.2 mg/m3 TWA 0.1 mg/m3 STEL
Iron Oxide	5 mg/m3 TWA 10 mg/m3 STEL (as fume)	5 mg/m3 TWA 10 mg/m3 STEL (as fume)	5 mg/m3 TWA
Manganese Oxide (MnO)	1 mg/m3 TWA 3 mg/m3 STEL (as fume)	5 mg/m3 TWA (as Mn compounds)	0.2 mg/m3 TWA
Molybdenum Trioxide (MoO₃) ¹⁾ (as molybdenum insoluble compounds)	10 mg/m3 TWA 20 mg/m3 STEL	10 mg/m3 TWA 10 mg/m3 STEL	3 mg/m3 TWA (as (respirable) 10 mg/m3 TWA (inhalable)
Nickel Oxide (NiO) (as nickel soluble compounds)	0.1 mg/m3 TWA 0.3 mg/m3 STEL	0.1 mg/m3 TWA 0.3 mg/m3 STEL	0.1 mg/m3 TWA
Niobium Oxide (NbO) 2)	None Established	None Established	None Established
Silica (SiO₂) (quartz)	0.1 mg/m3 TWA (respirable) 0.3 mg/m3 TWA (total dust)	300 particles/mL	0.025 mg/m3 TWA

¹⁾ Only in Molybdenum-alloyed grades.

²⁾ Only in Niobium-alloyed grades.

QUESTIONS 14, 15

PAINT		USED SINCE 9/1/201	.0		wa
PAINT		DESCRIPTION	GALLONS	MONTLY AVG.	MIXED ON SITE
E61A45	i	KEM FLASH PRIMER	2610	51.18	AS IS
E61A750	2	KEM FLASH 500	180	45.00	AS IS
E61A705	3	ULTRA BOND	280	70.00	AS IS
B67A5	4	2 PART EPOXY	75	25.00	MIXED
B67C5	5	CATALYST	75	25.00	MIXED
XYLENE	6		705	11.75	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
R7K54	7	REDUCER	27	9.00	

Questions 14,15

5 pagl

MATERIAL SAFETY DATA SHEET

E61A45 33 00 DATE OF PREPARATION Oct 23, 2014

SECTION 1 — PRODUCT AND COMPANY IDENTIFICATION

PRODUCT NUMBER

E61A45

PRODUCT NAME

KEM-FLASH® PRIME Metal Primer, Gray

MANUFACTURER'S NAME

THE SHERWIN-WILLIAMS COMPANY

101 Prospect Avenue N.W.

Cleveland, OH 44115

Telephone Numbers and Websites

www.oem.sherwin-williams.com
(216) 566-2902
(216) 566-2917
(800) 424-9300
cy ONLY (spill, leak, fire, exposure, or accident)

SECTION 2 — COMPOSITION/INFORMATION ON INGREDIENTS

% by Weight	CAS Number		Units	Vapor Pressure	
30	64742-89-8		Lt. Aliphatic Hydrocarbon Solvent		
		ACGIH TLV	300 PPM	12 mm	
		OSHA PEL	300 PPM		
6	64742-88-7	Med. Aliphatic Hydr	Med. Aliphatic Hydrocarbon Solvent		
		ACGIH TLV	100 PPM	1.27 mm	
		OSHA PEL	100 PPM		
0.2	100-41-4	Ethylbenzene			
		ACGIH TLV	20 PPM	7.1 mm	
		OSHA PEL	100 PPM		
		OSHA PEL	125 PPM STEL		
1	1330-20-7	Xylene			
		ACGIH TLV	100 PPM	5.9 mm	
		ACGIH TLV	150 PPM STEL		
		OSHA PEL	100 PPM		
		OSHA PEL	150 PPM STEL		
0.1	14808-60-7	Quartz			
		ACGIH TLV	0.025 mg/m3 as Resp. Dust		
		OSHA PEL	0.1 mg/m3 as Resp. Dust		
10	14807-96-6	Talc			
		ACGIH TLV	2 mg/m3 as Resp. Dust		
		OSHA PEL	2 mg/m3 as Resp. Dust		
18	7727-43-7	Barium Sulfate			
		ACGIH TLV	10 mg/m3 as Dust		
		OSHA PEL	10 mg/m3 Total Dust		
		OSHA PEL	5 mg/m3 Respirable Fraction		
8	13463-67-7	Titanium Dioxide			
		ACGIH TLV	10 mg/m3 as Dust		
		OSHA PEL	10 mg/m3 Total Dust		
		OSHA PEL	5 mg/m3 Respirable Fraction		
by Weight		Ingredier			
.89		Barium (a	s Ba; total)		

SECTION 3 — HAZARDS IDENTIFICATION

ROUTES OF EXPOSURE

INHALATION of vapor or spray mist. EYE or SKIN contact with the product, vapor or spray mist.

EFFECTS OF OVEREXPOSURE

EYES: Irritation.

SKIN: Prolonged or repeated exposure may cause irritation.

INHALATION: Irritation of the upper respiratory system.

HMIS Codes
Health 2*
Flammability 3
Reactivity 0

May cause nervous system depression. Extreme overexposure may result in unconsciousness and possibly death.

Prolonged overexposure to hazardous ingredients in Section 2 may cause adverse chronic effects to the following organs or systems:

- the liver
- the urinary system
- · the reproductive system

SIGNS AND SYMPTOMS OF OVEREXPOSURE

Headache, dizziness, nausea, and loss of coordination are indications of excessive exposure to vapors or spray mists.

Redness and itching or burning sensation may indicate eye or excessive skin exposure.

MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE

None generally recognized.

CANCER INFORMATION

For complete discussion of toxicology data refer to Section 11.

SECTION 4 — FIRST AID MEASURES

EYES: Flush eyes with large amounts of water for 15 minutes. Get medical attention.

SKIN: Wash affected area thoroughly with soap and water.
Remove contaminated clothing and launder before re-use.

INHALATION: If affected, remove from exposure. Restore breathing. Keep warm and quiet.

INGESTION: Do not induce vomiting. Get medical attention immediately.

SECTION 5 — FIRE FIGHTING MEASURES

FLASH POINT LEL UEL FLAMMABILITY CLASSIFICATION

50 °F PMCC 0.9 7.0 RED LABEL -- Flammable, Flash below 100 °F (38 °C)

EXTINGUISHING MEDIA

Carbon Dioxide, Dry Chemical, Foam

UNUSUAL FIRE AND EXPLOSION HAZARDS

Closed containers may explode when exposed to extreme heat.

Application to hot surfaces requires special precautions.

During emergency conditions overexposure to decomposition products may cause a health hazard. Symptoms may not be immediately apparent. Obtain medical attention.

SPECIAL FIRE FIGHTING PROCEDURES

Full protective equipment including self-contained breathing apparatus should be used.

Water spray may be ineffective. If water is used, fog nozzles are preferable. Water may be used to cool closed containers to prevent pressure build-up and possible autoignition or explosion when exposed to extreme heat.

SECTION 6 — ACCIDENTAL RELEASE MEASURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Remove all sources of ignition. Ventilate the area.

Remove with inert absorbent.

SECTION 7 — HANDLING AND STORAGE

STORAGE CATEGORY

DOL Storage Class IB

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE

Contents are FLAMMABLE. Keep away from heat, sparks, and open flame.

During use and until all vapors are gone: Keep area ventilated - Do not smoke - Extinguish all flames, pilot lights, and heaters - Turn off stoves, electric tools and appliances, and any other sources of ignition.

Consult NFPA Code. Use approved Bonding and Grounding procedures.

Keep container closed when not in use. Transfer only to approved containers with complete and appropriate labeling. Do not take internally. Keep out of the reach of children.

SECTION 8 — EXPOSURE CONTROLS/PERSONAL PROTECTION

PRECAUTIONS TO BE TAKEN IN USE

Use only with adequate ventilation.

Avoid contact with skin and eyes. Avoid breathing vapor and spray mist.

Wash hands after using.

This coating may contain materials classified as nuisance particulates (listed "as Dust" in Section 2) which may be present at hazardous levels only during sanding or abrading of the dried film. If no specific dusts are listed in Section 2, the applicable limits for nuisance dusts are ACGIH TLV 10 mg/m3 (total dust), 3 mg/m3 (respirable fraction), OSHA PEL 15 mg/m3 (total dust), 5 mg/m3 (respirable fraction).

VENTILATION

Local exhaust preferable. General exhaust acceptable if the exposure to materials in Section 2 is maintained below applicable exposure limits. Refer to OSHA Standards 1910.94, 1910.107, 1910.108.

RESPIRATORY PROTECTION

If personal exposure cannot be controlled below applicable limits by ventilation, wear a properly fitted organic vapor/particulate respirator approved by NIOSH/MSHA for protection against materials in Section 2.

When sanding, wirebrushing, abrading, burning or welding the dried film, wear a particulate respirator approved by NIOSH/MSHA for protection against non-volatile materials in Section 2.

PROTECTIVE GLOVES

Wear gloves which are recommended by glove supplier for protection against materials in Section 2.

EYE PROTECTION

Wear safety spectacles with unperforated sideshields.

OTHER PRECAUTIONS

Intentional misuse by deliberately concentrating and inhaling the contents can be harmful or fatal.

SECTION 9 — PHYSICAL AND CHEMICAL PROPERTIES

PRODUCT WEIGHT 10.24 lb/gal

SPECIFIC GRAVITY 1.23

24 lb/gal 1227 g/l

BOILING POINT
MELTING POINT

240 - 395 °F 115 - 201 °C

VOLATILE VOLUME

Not Available 63%

EVAPORATION RATE

Slower than

VAPOR DENSITY

ether Heavier than air

SOLUBILITY IN WATER Not Available

VOLATILE ORGANIC COMPOUNDS (VOC Theoretical - As Packaged)

3.94 lb/gal 473 g/l

Less Water and Federally Exempt Solvents

3.94 lb/gal 472 g/l Emitted VOC

SECTION 10 — STABILITY AND REACTIVITY

STABILITY — Stable CONDITIONS TO AVOID

None known.

INCOMPATIBILITY

None known.

HAZARDOUS DECOMPOSITION PRODUCTS

By fire: Carbon Dioxide, Carbon Monoxide, Oxides of Metals in Section 2

HAZARDOUS POLYMERIZATION

Will not occur

SECTION 11 — TOXICOLOGICAL INFORMATION

CHRONIC HEALTH HAZARDS

Reports have associated repeated and prolonged overexposure to solvents with permanent brain and nervous system damage. Ethylbenzene is classified by IARC as possibly carcinogenic to humans (2B) based on inadequate evidence in humans and sufficient evidence in laboratory animals. Lifetime inhalation exposure of rats and mice to high ethylbenzene concentrations resulted in increases in certain types of cancer, including kidney tumors in rats and lung and liver tumors in mice. These effects were not observed in animals exposed to lower concentrations. There is no evidence that ethylbenzene causes cancer in humans.

Crystalline Silica (Quartz, Cristobalite) is listed by IARC and NTP. Long term exposure to high levels of silica dust, which can occur only when sanding or abrading the dry film, may cause lung damage (silicosis) and possibly cancer.

IARC's Monograph No. 93 reports there is sufficient evidence of carcinogenicity in experimental rats exposed to titanium dioxide but inadequate evidence for carcinogenicity in humans and has assigned a Group 2B rating. In addition, the IARC summary concludes, "No significant exposure to titanium dioxide is thought to occur during the use of products in which titanium is bound to other materials, such as paint."

TOXICOLOGY DATA

CAS No.	Ingredient Name			
64742-89-8	Lt. Aliphatic Hydroca	rbon Solvent		**
	-	LC50 RAT	4HR	Not Available
		LD50 RAT		Not Available
64742-88-7	Med. Aliphatic Hydro	carbon Solvent		100
		LC50 RAT	4HR	Not Available
		LD50 RAT		Not Available
100-41-4	Ethylbenzene			
		LC50 RAT	4HR	Not Available
		LD50 RAT		3500 mg/kg
1330-20-7	Xylene			
		LC50 RAT	4HR	5000 ppm
		LD50 RAT		4300 mg/kg
14808-60-7	Quartz			The state of the s
		LC50 RAT	4HR	Not Available
		LD50 RAT		Not Available
14807-96-6	Talc			
		LC50 RAT	4HR	Not Available
		LD50 RAT		Not Available
7727-43-7	Barium Sulfate		······································	
		LC50 RAT	4HR	Not Available
		LD50 RAT		Not Available
13463-67-7	Titanium Dioxide		······································	· · · · · · · · · · · · · · · · · · ·
		LC50 RAT	4HR	Not Available
		LD50 RAT		Not Available

SECTION 12 — ECOLOGICAL INFORMATION

ECOTOXICOLOGICAL INFORMATION

No data available.

SECTION 13 — DISPOSAL CONSIDERATIONS

WASTE DISPOSAL METHOD

Waste from this product may be hazardous as defined under the Resource Conservation and Recovery Act (RCRA) 40 CFR 261. Waste must be tested for ignitability and extractability to determine the applicable EPA hazardous waste numbers. Incinerate in approved facility. Do not incinerate closed container. Dispose of in accordance with Federal, State/Provincial, and Local regulations regarding pollution.

SECTION 14 — TRANSPORT INFORMATION

Multi-modal shipping descriptions are provided for informational purposes and do not consider container sizes. The presence of a shipping description for a particular mode of transport (ocean, air, etc.), does not indicate that the product is packaged suitably for that mode of transport. All packaging must be reviewed for suitability prior to shipment, and compliance with the applicable regulations is the sole responsibility of the person offering the product for transport.

US Ground (DOT)

5 Liters (1.3 Gallons) and Less may be Classed as LTD. QTY. (PAINT OR RELATED).

Larger Containers are Regulated as:

UN1263, PAINT, 3, PG II, (ERG#128)

DOT (Dept of Transportation) Hazardous Substances & Reportable Quantities

Xylenes (isomers and mixture) 100 lb RQ

Bulk Containers may be Shipped as (check reportable quantities):

UN1263, PAINT, 3, PG II, (ERG#128)

Canada (TDG)

UN1263, PAINT, CLASS 3, PG II, LIMITED QUANTITY, (ERG#128)

IMC

5 Liters (1.3 Gallons) and Less may be Shipped as Limited Quantity. UN1263, PAINT, CLASS 3, PG II, (10 C c.c.), EmS F-E, <u>S-E</u>

IATA/ICAO

UN1263, PAINT, 3, PG II

SECTION 15 — REGULATORY INFORMATION

SARA 313 (40 CFR 372.65C) SUPPLIER NOTIFICATION

CAS No.	CHEMICAL/COMPOUND	% by WT	% Element
100-41-4	Ethylbenzene	0.2	
1330-20-7	Xylene	1	
	Zinc Compound	2	1.2
	Barium Compound	2	0.8

CALIFORNIA PROPOSITION 65

WARNING: This product contains chemicals known to the State of California to cause cancer and birth defects or other reproductive harm. TSCA CERTIFICATION

All chemicals in this product are listed, or are exempt from listing, on the TSCA Inventory.

SECTION 16 — OTHER INFORMATION

This product has been classified in accordance with the hazard criteria of the Canadian Controlled Products Regulations (CPR) and the MSDS contains all of the information required by the CPR.

The above information pertains to this product as currently formulated, and is based on the information available at this time. Addition of reducers or other additives to this product may substantially alter the composition and hazards of the product. Since conditions of use are outside our control, we make no warranties, express or implied, and assume no liability in connection with any use of this information.

2 (5 piges)

MATERIAL SAFETY DATA SHEET

E61A750 05 00 DATE OF PREPARATION May 20, 2015

SECTION 1 — PRODUCT AND COMPANY IDENTIFICATION

PRODUCT NUMBER

E61A750

PRODUCT NAME

KEM-FLASH® 500 Primer, Light Gray

MANUFACTURER'S NAME

THE SHERWIN-WILLIAMS COMPANY 101 Prospect Avenue N.W. Cleveland, OH 44115

Telephone Numbers and Websites

reseptione numbers and trepsite	3
Product Information	www.oem.sherwin-williams.com
Regulatory Information	(216) 566-2902
Medical Emergency	(216) 566-2917
Transportation Emergency*	(800) 424-9300
*for Chemical Emergenc	y ONLY (spill, leak, fire, exposure, or accident)

% by Weight	CAS Number		Units	Vapor Pressure
0.1	100-41-4	Ethylbenzene		
		ACGIH TLV	20 PPM	7.1 mm
		OSHA PEL	100 PPM	
		OSHA PEL	125 PPM STEL	
3	64742-95-6	Light Aromatic Hydro	carbons	
		ACGIH TLV	Not Available	3.8 mm
		OSHA PEL	Not Available	
1	108-67-8	1,3,5-Trimethylbenzer	ne	
		ACGIH TLV	25 PPM	2 mm
		OSHA PEL	25 PPM	
4	95-63-6	1,2,4-Trimethylbenzen	ne	
		ACGIH TLV	25 PPM	2.03 mm
		OSHA PEL	25 PPM	
15	108-10-1	Methyl Isobutyl Keton	le .	
		ACGIH TLV	50 PPM	16 mm
		ACGIH TLV	75 PPM STEL	
		OSHA PEL	50 PPM	•
		OSHA PEL	75 PPM STEL	
5	14807-96-6	Talc		
		ACGIH TLV	2 mg/m3 as Resp. Dust	
		OSHA PEL	2 mg/m3 as Resp. Dust	
24	1317-65-3	Calcium Carbonate		
		ACGIH TLV	10 mg/m3 as Dust	
		OSHA PEL	10 mg/m3 Total Dust	
		OSHA PEL	5 mg/m3 Respirable Fraction	
10	7727-43-7	Barium Sulfate		
		ACGIH TLV	10 mg/m3 as Dust	
		OSHA PEL	10 mg/m3 Total Dust	
		OSHA PEL	5 mg/m3 Respirable Fraction	
9	13463-67-7	Titanium Dioxide	1	
		ACGIH TLV	10 mg/m3 as Dust	
		OSHA PEL	10 mg/m3 Total Dust	•
		OSHA PEL	5 mg/m3 Respirable Fraction	

SECTION 3 — HAZARDS IDENTIFICATION

ROUTES OF EXPOSURE

INHALATION of vapor or spray mist.

EYE or SKIN contact with the product, vapor or spray mist.

EFFECTS OF OVEREXPOSURE

EYES: Irritation.

SKIN: Prolonged or repeated exposure may cause irritation.

INHALATION: Irritation of the upper respiratory system.

May cause nervous system depression. Extreme overexposure may result in unconsciousness and possibly death.

Prolonged overexposure to hazardous ingredients in Section 2 may cause adverse chronic effects to the following organs or systems:

- the liver
- the urinary system
- the reproductive system

SIGNS AND SYMPTOMS OF OVEREXPOSURE

Headache, dizziness, nausea, and loss of coordination are indications of excessive exposure to vapors or spray mists.

Redness and itching or burning sensation may indicate eye or excessive skin exposure.

MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE

None generally recognized.

CANCER INFORMATION

For complete discussion of toxicology data refer to Section 11.

SECTION 4 — FIRST AID MEASURES

EYES: Flush eyes with large amounts of water for 15 minutes. Get medical attention.

SKIN: Wash affected area thoroughly with soap and water.

Remove contaminated clothing and launder before re-use.

INHALATION: If affected, remove from exposure. Restore breathing. Keep warm and quiet.

INGESTION: Do not induce vomiting. Get medical attention immediately.

SECTION 5 — FIRE FIGHTING MEASURES

FLASH POINT LEL UEL FLAMMABILITY CLASSIFICATION

65 °F PMCC 0.7 7.5 RED LABEL -- Flammable, Flash below 100 °F (38 °C)

EXTINGUISHING MEDIA

Carbon Dioxide, Dry Chemical, Foam

UNUSUAL FIRE AND EXPLOSION HAZARDS

Closed containers may explode when exposed to extreme heat.

Application to hot surfaces requires special precautions.

During emergency conditions overexposure to decomposition products may cause a health hazard. Symptoms may not be immediately apparent. Obtain medical attention.

SPECIAL FIRE FIGHTING PROCEDURES

Full protective equipment including self-contained breathing apparatus should be used.

Water spray may be ineffective. If water is used, fog nozzles are preferable. Water may be used to cool closed containers to prevent pressure build-up and possible autoignition or explosion when exposed to extreme heat.

SECTION 6 — ACCIDENTAL RELEASE MEASURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Remove all sources of ignition. Ventilate the area.

Remove with inert absorbent.

SECTION 7 — HANDLING AND STORAGE

STORAGE CATEGORY

DOL Storage Class IB

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE

Contents are FLAMMABLE. Keep away from heat, sparks, and open flame.

During use and until all vapors are gone: Keep area ventilated - Do not smoke - Extinguish all flames, pilot lights, and heaters - Turn off stoves, electric tools and appliances, and any other sources of ignition.

Consult NFPA Code. Use approved Bonding and Grounding procedures.

Keep container closed when not in use. Transfer only to approved containers with complete and appropriate labeling. Do not take internally. Keep out of the reach of children.

SECTION 8 — EXPOSURE CONTROLS/PERSONAL PROTECTION

PRECAUTIONS TO BE TAKEN IN USE

Use only with adequate ventilation.

Avoid contact with skin and eyes. Avoid breathing vapor and spray mist.

HMIS Codes

3

Health 2*

Reactivity 0

Flammability

Wash hands after using.

This coating may contain materials classified as nuisance particulates (listed "as Dust" in Section 2) which may be present at hazardous levels only during sanding or abrading of the dried film. If no specific dusts are listed in Section 2, the applicable limits for nuisance dusts are ACGIH TLV 10 mg/m3 (total dust), 3 mg/m3 (respirable fraction), OSHA PEL 15 mg/m3 (total dust), 5 mg/m3 (respirable fraction).

VENTILATION

Local exhaust preferable. General exhaust acceptable if the exposure to materials in Section 2 is maintained below applicable exposure limits. Refer to OSHA Standards 1910.94, 1910.107, 1910.108.

RESPIRATORY PROTECTION

If personal exposure cannot be controlled below applicable limits by ventilation, wear a properly fitted organic vapor/particulate respirator approved by NIOSH/MSHA for protection against materials in Section 2.

When sanding or abrading the dried film, wear a dust/mist respirator approved by NIOSH/MSHA for dust which may be generated from this product, underlying paint, or the abrasive.

PROTECTIVE GLOVES

Wear gloves which are recommended by glove supplier for protection against materials in Section 2.

EYE PROTECTION

Wear safety spectacles with unperforated sideshields.

OTHER PRECAUTIONS

Intentional misuse by deliberately concentrating and inhaling the contents can be harmful or fatal.

SECTION 9 — PHYSICAL AND CHEMICAL PROPERTIES

PRODUCT WEIGHT 12.82 lb/gal

1536 g/l

SPECIFIC GRAVITY 1.54

237 - 360 °F **BOILING POINT**

113 - 182 °C

MELTING POINT VOLATILE VOLUME Not Available 47%

EVAPORATION RATE

Slower than ether

VAPOR DENSITY

Heavier than air

SOLUBILITY IN WATER Not Available

VOLATILE ORGANIC COMPOUNDS (VOC Theoretical - As Packaged)

390 g/l 3.25 lb/gal

Less Water and Federally Exempt Solvents

3.25 lb/gal 389 g/l **Emitted VOC**

SECTION 10 — STABILITY AND REACTIVITY

STABILITY - Stable **CONDITIONS TO AVOID**

None known.

INCOMPATIBILITY

None known.

HAZARDOUS DECOMPOSITION PRODUCTS

By fire: Carbon Dioxide, Carbon Monoxide, Phosphoric Acid Fumes, Oxides of Phosphorus

HAZARDOUS POLYMERIZATION

Will not occur

SECTION 11 — TOXICOLOGICAL INFORMATION

CHRONIC HEALTH HAZARDS

Reports have associated repeated and prolonged overexposure to solvents with permanent brain and nervous system damage. Ethylbenzene is classified by IARC as possibly carcinogenic to humans (2B) based on inadequate evidence in humans and sufficient evidence in laboratory animals. Lifetime inhalation exposure of rats and mice to high ethylbenzene concentrations resulted in increases in certain types of cancer, including kidney tumors in rats and lung and liver tumors in mice. These effects were not observed in animals exposed to lower concentrations. There is no evidence that ethylbenzene causes cancer in humans,

IARC's Monograph No. 93 reports there is sufficient evidence of carcinogenicity in experimental rats exposed to titanium dioxide but inadequate evidence for carcinogenicity in humans and has assigned a Group 2B rating. In addition, the IARC summary concludes, "No significant exposure to titanium dioxide is thought to occur during the use of products in which titanium is bound to other materials, such as paint."

TOXICOLOGY DATA

CAS No.	Ingredient Name			glivan
100-41-4	Ethylbenzene			
	LC50 RAT	4HR	Not Available	
	LD50 RAT		3500 mg/kg	
64742-95-6	Light Aromatic Hydrocarbons			
	LC50 RAT	4HR	Not Available	
	LD50 RAT		Not Available	
08-67-8	1,3,5-Trimethylbenzene			
	LC50 RAT	4HR	Not Available	
	LD50 RAT		Not Available	
5-63-6	1,2,4-Trimethylbenzene			
	LC50 RAT	4HR	Not Available	
	LD50 RAT		Not Available	
108-10-1	Methyl Isobutyl Ketone			
	LC50 RAT	4HR	Not Available	
	LD50 RAT		2080 mg/kg	
14807-96-6	Talc			· · · · · · · · · · · · · · · · · · ·
	LC50 RAT	4HR	Not Available	
	LD50 RAT		Not Available	
1317-65-3	Calcium Carbonate			
	LC50 RAT	4HR	Not Available	
	LD50 RAT		Not Available	
727-43-7	Barium Sulfate		· · · · · · · · · · · · · · · · · · ·	
	LC50 RAT	4HR	Not Available	
	LD50 RAT		Not Available	
13463-67-7	Titanium Dioxide			
	LC50 RAT	4HR	Not Available	
	LD50 RAT		Not Available	

SECTION 12 — ECOLOGICAL INFORMATION

ECOTOXICOLOGICAL INFORMATION

No data available.

SECTION 13 — DISPOSAL CONSIDERATIONS

WASTE DISPOSAL METHOD

Waste from this product may be hazardous as defined under the Resource Conservation and Recovery Act (RCRA) 40 CFR 261. Waste must be tested for ignitability to determine the applicable EPA hazardous waste numbers.

Incinerate in approved facility. Do not incinerate closed container. Dispose of in accordance with Federal, State/Provincial, and Local regulations regarding pollution.

SECTION 14 — TRANSPORT INFORMATION

Multi-modal shipping descriptions are provided for informational purposes and do not consider container sizes. The presence of a shipping description for a particular mode of transport (ocean, air, etc.), does not indicate that the product is packaged suitably for that mode of transport. All packaging must be reviewed for suitability prior to shipment, and compliance with the applicable regulations is the sole responsibility of the person offering the product for transport.

US Ground (DOT)

5 Liters (1.3 Gallons) and Less may be Classed as LTD. QTY. (PAINT OR RELATED).

Larger Containers are Regulated as:

UN1263, PAINT, 3, PG II, (ERG#128)

DOT (Dept of Transportation) Hazardous Substances & Reportable Quantities

Methyl isobutyl ketone 5000 lb RQ

Xylenes (isomers and mixture) 100 lb RQ

Bulk Containers may be Shipped as (check reportable quantities):

UN1263, PAINT, 3, PG II, (ERG#128)

Canada (TDG)

UN1263, PAINT, CLASS 3, PG II, LIMITED QUANTITY, (ERG#128)

IMO

5 Liters (1.3 Gallons) and Less may be Shipped as Limited Quantity. UN1263, PAINT, CLASS 3, PG II, (18 C c.c.), EmS F-E, S-E

IMO

5 Liters (1.3 Gallons) and Less may be Shipped as Limited Quantity. UN1263, PAINT, CLASS 3, PG II, (18 C c.c.), EmS F-E, S-E

IATA/ICAO

UN1263, PAINT, 3, PG II

SECTION 15 — REGULATORY INFORMATION

SARA 313 (40 CFR 372.65C) SUPPLIER NOTIFICATION

CAS No.	CHEMICAL/COMPOUND	% by WT	% Element
100-41-4	Ethylbenzene	0.1	
95-63-6	1,2,4-Trimethylbenzene	4	
108-10-1	Methyl Isobutyl Ketone	15	
	Zinc Compound	7	3.4

CALIFORNIA PROPOSITION 65

WARNING: This product contains chemicals known to the State of California to cause cancer and birth defects or other reproductive harm. **TSCA CERTIFICATION**

All chemicals in this product are listed, or are exempt from listing, on the TSCA Inventory.

SECTION 16 — OTHER INFORMATION

This product has been classified in accordance with the hazard criteria of the Canadian Controlled Products Regulations (CPR) and the MSDS contains all of the information required by the CPR.

The above information pertains to this product as currently formulated, and is based on the information available at this time. Addition of reducers or other additives to this product may substantially alter the composition and hazards of the product. Since conditions of use are outside our control, we make no warranties, express or implied, and assume no liability in connection with any use of this information.

3 (5 pyls)

MATERIAL SAFETY DATA SHEET

E61A705 10 00

DATE OF PREPARATION Aug 23, 2014

SECTION 1 — PRODUCT AND COMPANY IDENTIFICATION

PRODUCT NUMBER

E61A705

PRODUCT NAME

KEM FLASH® ULTRA-BOND® Primer, Gray

MANUFACTURER'S NAME

THE SHERWIN-WILLIAMS COMPANY 101 Prospect Avenue N.W.

Cleveland, OH 44115

Telephone Numbers and Websites

Product Information	www.oem.sherwin-williams.com
Regulatory Information	(216) 566-2902
Medical Emergency	(216) 566-2917
Transportation Emergency*	(800) 424-9300
	y ONLY (spill, leak, fire, exposure, or
	accident)

SECTION 2 — COMPOSITION/INFORMATION ON INGREDIENTS

% by Weight	CAS Number	Ingredient	Units	Vapor Pressure
0.1	100-41-4	Ethylbenzene		
		ACGIH TLV	20 PPM	7.1 mm
		OSHA PEL	100 PPM	
		OSHA PEL	125 PPM STEL	
10	108-10-1	Methyl Isobutyl Ketor	ne	
		ACGIH TLV	50 PPM	16 mm
		ACGIH TLV	75 PPM STEL	
		OSHA PEL	50 PPM	
		OSHA PEL	75 PPM STEL	•
16	123-86-4	n-Butyl Acetate		
		ACGIH TLV	150 PPM	10 mm
		ACGIH TLV	200 PPM STEL	
		OSHA PEL	150 PPM	
		OSHA PEL	200 PPM STEL	
1	7631-86-9	Amorphous Silica		
		ACGIH TLV	10 mg/m3 as Dust	
		OSHA PEL	6 mg/m3 as Dust	
33	1317-65-3	Calcium Carbonate		
		ACGIH TLV	10 mg/m3 as Dust	
		OSHA PEL	10 mg/m3 Total Dust	
		OSHA PEL	5 mg/m3 Respirable Fraction	
10	13463-67-7	Titanium Dioxide		
		ACGIH TLV	10 mg/m3 as Dust	
		OSHA PEL	10 mg/m3 Total Dust	
		OSHA PEL	5 mg/m3 Respirable Fraction	
3	1314-13-2	Zinc Oxide		
		ACGIH TLV	Not Available	
		OSHA PEL	Not Available	

SECTION 3 — HAZARDS IDENTIFICATION

ROUTES OF EXPOSURE

INHALATION of vapor or spray mist. EYE or SKIN contact with the product, vapor or spray mist.

HMIS (odes
Health	2*
Flammability	3
Reactivity	0

EFFECTS OF OVEREXPOSURE

EYES: Irritation.

SKIN: Prolonged or repeated exposure may cause irritation.

INHALATION: Irritation of the upper respiratory system.

May cause nervous system depression. Extreme overexposure may result in unconsciousness and possibly death.

Prolonged overexposure to hazardous ingredients in Section 2 may cause adverse chronic effects to the following organs or systems:

the urinary system

the hematopoietic (blood-forming) system

SIGNS AND SYMPTOMS OF OVEREXPOSURE

Headache, dizziness, nausea, and loss of coordination are indications of excessive exposure to vapors or spray mists.

Redness and itching or burning sensation may indicate eye or excessive skin exposure.

MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE

None generally recognized.

CANCER INFORMATION

For complete discussion of toxicology data refer to Section 11.

SECTION 4 — FIRST AID MEASURES

EYES: Flush eyes with large amounts of water for 15 minutes. Get medical attention.

SKIN: Wash affected area thoroughly with soap and water.

Remove contaminated clothing and launder before re-use.

INHALATION: If affected, remove from exposure. Restore breathing. Keep warm and quiet.

INGESTION: Do not induce vomiting. Get medical attention immediately.

SECTION 5 — FIRE FIGHTING MEASURES

FLASH POINT LEL UEL FLAMMABILITY CLASSIFICATION

61 °F PMCC 1.4 7.6 RED LABEL -- Flammable, Flash below 100 °F (38 °C)

EXTINGUISHING MEDIA

Carbon Dioxide, Dry Chemical, Foam

UNUSUAL FIRE AND EXPLOSION HAZARDS

Closed containers may explode when exposed to extreme heat.

Application to hot surfaces requires special precautions.

During emergency conditions overexposure to decomposition products may cause a health hazard. Symptoms may not be immediately apparent. Obtain medical attention.

SPECIAL FIRE FIGHTING PROCEDURES

Full protective equipment including self-contained breathing apparatus should be used.

Water spray may be ineffective. If water is used, fog nozzles are preferable. Water may be used to cool closed containers to prevent pressure build-up and possible autoignition or explosion when exposed to extreme heat.

SECTION 6 — ACCIDENTAL RELEASE MEASURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Remove all sources of ignition. Ventilate the area.

Remove with inert absorbent.

SECTION 7 — HANDLING AND STORAGE

STORAGE CATEGORY

DOL Storage Class IB

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE

Contents are FLAMMABLE. Keep away from heat, sparks, and open flame.

During use and until all vapors are gone: Keep area ventilated - Do not smoke - Extinguish all flames, pilot lights, and heaters - Turn off stoves, electric tools and appliances, and any other sources of ignition.

Consult NFPA Code. Use approved Bonding and Grounding procedures.

Keep container closed when not in use. Transfer only to approved containers with complete and appropriate labeling. Do not take internally. Keep out of the reach of children.

SECTION 8 — EXPOSURE CONTROLS/PERSONAL PROTECTION

PRECAUTIONS TO BE TAKEN IN USE

Use only with adequate ventilation.

Avoid contact with skin and eyes. Avoid breathing vapor and spray mist.

Wash hands after using.

This coating may contain materials classified as nuisance particulates (listed "as Dust" in Section 2) which may be present at hazardous levels only during sanding or abrading of the dried film. If no specific dusts are listed in Section 2, the applicable limits for nuisance dusts are ACGIH TLV 10 mg/m3 (total dust), 3 mg/m3 (respirable fraction).

VENTILATION

Local exhaust preferable. General exhaust acceptable if the exposure to materials in Section 2 is maintained below applicable exposure limits. Refer to OSHA Standards 1910.94, 1910.107, 1910.108.

RESPIRATORY PROTECTION

If personal exposure cannot be controlled below applicable limits by ventilation, wear a properly fitted organic vapor/particulate respirator approved by NIOSH/MSHA for protection against materials in Section 2.

When sanding or abrading the dried film, wear a dust/mist respirator approved by NIOSH/MSHA for dust which may be generated from this product, underlying paint, or the abrasive.

PROTECTIVE GLOVES

Wear gloves which are recommended by glove supplier for protection against materials in Section 2.

EYE PROTECTION

Wear safety spectacles with unperforated sideshields.

OTHER PRECAUTIONS

Intentional misuse by deliberately concentrating and inhaling the contents can be harmful or fatal.

SECTION 9 — PHYSICAL AND CHEMICAL PROPERTIES

PRODUCT WEIGHT 11.78 lb/gal

1411 g/l

SPECIFIC GRAVITY 1.42

BOILING POINT 237 - 264 °F

113 - 128 °C

MELTING POINT

Not Available

VOLATILE VOLUME

47%

EVAPORATION RATE

Slower than

ether

VAPOR DENSITY

Heavier than air

SOLUBILITY IN WATER Not Available

VOLATILE ORGANIC COMPOUNDS (VOC Theoretical - As Packaged)

3.32 lb/gal 398 g/l Less Water and Federally Exempt Solvents 3.32 lb/gal 398 g/l

Emitted VOC

SECTION 10 — STABILITY AND REACTIVITY

STABILITY --- Stable **CONDITIONS TO AVOID**

None known.

INCOMPATIBILITY

None known.

HAZARDOUS DECOMPOSITION PRODUCTS

By fire: Carbon Dioxide, Carbon Monoxide

HAZARDOUS POLYMERIZATION

Will not occur

SECTION 11 — TOXICOLOGICAL INFORMATION

CHRONIC HEALTH HAZARDS

Reports have associated repeated and prolonged overexposure to solvents with permanent brain and nervous system damage. Ethylbenzene is classified by IARC as possibly carcinogenic to humans (2B) based on inadequate evidence in humans and sufficient evidence in laboratory animals. Lifetime inhalation exposure of rats and mice to high ethylbenzene concentrations resulted in increases in certain types of cancer, including kidney tumors in rats and lung and liver tumors in mice. These effects were not observed in animals exposed to lower concentrations. There is no evidence that ethylbenzene causes cancer in humans.

IARC's Monograph No. 93 reports there is sufficient evidence of carcinogenicity in experimental rats exposed to titanium dioxide but inadequate evidence for carcinogenicity in humans and has assigned a Group 2B rating. In addition, the IARC summary concludes, "No significant exposure to titanium dioxide is thought to occur during the use of products in which titanium is bound to other materials, such as paint."

TOXICOLOGY DATA

100-41-4	Ethylbenzene			
	•	LC50 RAT	4HR	Not Available
		LD50 RAT		3500 mg/kg
108-10-1	Methyl Isobutyl Ketone			3
	•	LC50 RAT	4HR	Not Available
		LD50 RAT		2080 mg/kg
123-86-4	n-Butyl Acetate			**************************************
	-	LC50 RAT	4HR	2000 ppm
		LD50 RAT		13100 mg/kg
7631-86-9	Amorphous Silica			
		LC50 RAT	4HR	Not Available
		LD50 RAT		Not Available
1317-65-3	Calcium Carbonate			
		LC50 RAT	4HR	Not Available
		LD50 RAT		Not Available
13463-67-7	Titanium Dîoxide			
		LC50 RAT	4HR	Not Available
		LD50 RAT		Not Available
1314-13-2	Zinc Oxide			
		LC50 RAT	4HR	Not Available
		LD50 RAT		Not Available

SECTION 12 — ECOLOGICAL INFORMATION

ECOTOXICOLOGICAL INFORMATION

No data available.

SECTION 13 — DISPOSAL CONSIDERATIONS

WASTE DISPOSAL METHOD

Waste from this product may be hazardous as defined under the Resource Conservation and Recovery Act (RCRA) 40 CFR 261. Waste must be tested for ignitability to determine the applicable EPA hazardous waste numbers.

Incinerate in approved facility. Do not incinerate closed container. Dispose of in accordance with Federal, State/Provincial, and Local regulations regarding pollution.

SECTION 14 — TRANSPORT INFORMATION

Multi-modal shipping descriptions are provided for informational purposes and do not consider container sizes. The presence of a shipping description for a particular mode of transport (ocean, air, etc.), does not indicate that the product is packaged suitably for that mode of transport. All packaging must be reviewed for suitability prior to shipment, and compliance with the applicable regulations is the sole responsibility of the person offering the product for transport.

US Ground (DOT)

5 Liters (1.3 Gallons) and Less may be Classed as LTD, QTY, (PAINT OR RELATED).

Larger Containers are Regulated as:

UN1263, PAINT, 3, PG II, (ERG#128)

DOT (Dept of Transportation) Hazardous Substances & Reportable Quantities

n-Butyl acetate 5000 lb RQ

Xylenes (isomers and mixture) 100 lb RQ

Bulk Containers may be Shipped as (check reportable quantities):

UN1263, PAINT, 3, PG II, (ERG#128)

Canada (TDG)

UN1263, PAINT, CLASS 3, PG II, LIMITED QUANTITY, (ERG#128)

IMC

5 Liters (1.3 Gallons) and Less may be Shipped as Limited Quantity. UN1263, PAINT, CLASS 3, PG II, MARINE POLLUTANT, (16 C c.c.), (ZINC

OXIDE), EmS F-E, S-E

IATA/ICAO

UN1263, PAINT, 3, PG II

SECTION 15 — REGULATORY INFORMATION

SARA 313 (40 CFR 372.65C) SUPPLIER NOTIFICATION

CAS No.	CHEMICAL/COMPOUND	% by WT	% Element
100-41-4	Ethylbenzene	0.1	
108-10-1	Methyl Isobutyl Ketone	10	
	Zinc Compound	6	3.5

CALIFORNIA PROPOSITION 65


WARNING: This product contains chemicals known to the State of California to cause cancer and birth defects or other reproductive harm. TSCA CERTIFICATION

All chemicals in this product are listed, or are exempt from listing, on the TSCA Inventory.

SECTION 16 — OTHER INFORMATION

This product has been classified in accordance with the hazard criteria of the Canadian Controlled Products Regulations (CPR) and the MSDS contains all of the information required by the CPR.

The above information pertains to this product as currently formulated, and is based on the information available at this time. Addition of reducers or other additives to this product may substantially alter the composition and hazards of the product. Since conditions of use are outside our control, we make no warranties, express or implied, and assume no liability in connection with any use of this information.





Marine **Coatings**

PART G **B67A5** PART G **B67H5** PART G **B67R5** PART G B67WJ5000 PART H **B67V5**

LIGHT GRAY TAN RED OXIDE WHITE HARDENER

Revised: Sept 8, 2015

PRODUCT INFORMATION

4.45

PRODUCT DESCRIPTION

RECOATABLE EPOXY PRIMER is a rust inhibitive high build catalyzed polyamide/bisphenol A epoxy primer designed for fast dry and quick or extended recoatability.

Meets Class A requirements for Slip Coefficient, .50 (Red Oxide only) Long pot life
High build coating for economical application
One year recoatability
Low temperature application - down to 35°F (1.5°C)
Corrosion resistant (contains zinc phosphate)
Outstanding application properties

PRODUCT CHARACTERISTICS

Finish:

Flat

Color:

Red Oxide, Tan, Light Gray, White

Volume Solids:

65% ± 4%, mixed

Weight Solids:

81% ± 2%, mixed

VOC (EPA Method 24):

Unreduced: Reduced 5%: <320 g/L; 2.67 lb/gal <340 g/L; 2.88 lb/gal

Mix Ratio:

1:1 by volume

	Recommended Spre	ading I	Rate pe	r coat:	
		Mini	imum	Maxi	mum
	Wet mils (microns)	6.0	(150)	9.0	(225)
	Dry mils (microns)	4.0*	(100)	6.0*	(150)
	~Coverage sq ft/gal (m²/L)	175	(4.3)	260	(6.4)
	Theoretical coverage sq ft/gal (m²/L) @ 1 mil / 25 microns dft *See Performance Tips section	1040	(25.5)		. ,
i					

NOTE: Brush or roll application may require multiple coats to achieve maximum film thickness and uniformity of appearance.

Drying Schedule @ 6.0 mils wet (150 microns): @ 35°F/1.5°C @ 77°F/25°C @ 120°F/49°C

50% RH To touch: 1 hour 15 minutes 10 minutes Tack free: 2 hours 30 minutes 15 minutes To recoat: minimum: 6 hours 2 hours 30 minutes maximum: 1 year 1 vear 1 year To cure: 14 days 14 days 2 days

If maximum recoat time is exceeded, abrade surface before recoating. Drying time is temperature, humidity, and film thickness dependent.

Pot Life: 8+ hours 8 hours 3 hours Sweat-in-time: 1 hour 30 minutes 10 minutes

Shelf Life:

36 months, unopened Store indoors at 40°F (4.5°C) to 100°F Store

(38°C).

Flash Point:

80°F (27°C), PMCC, mixed

Reducer/Clean Up: Below 80°F (27°C): Above 80°F (27°C):

Reducer #54, R7K54 or R7K111 Reducer #100, R7K100, R7K104, or R7K111

In California Reducer R7K111

For use as a shop or field applied epoxy primer where a variable recoat window is required due to construction schedules, distribution logistics and environmental considerations. Affords flexibility in projects when completion schedules cannot be specified.

Primer for structural steel

· Marine applications

Paper mills

Storage tanks

Power plants

Suitable for use in USDA inspected facilities Nuclear Power Plants • DOE Nuclea Nuclear Power Plants • DOE Nuclear Fuel Facilities
Nuclear fabrication shops • DOE Nuclear Weapons Facilities
This product meets specific design requirements for non-safety related nuclear plant applications in Level II, III and Balance
of Plant, and DOE nuclear facilities*.

RECOMMENDED USES

Nuclear qualifications are NRC license specific to the facility.

Performance Characteristics

Substrate*: Steel

Surface Preparation*: SSPC-SP6/NACE 3

System Tested*:

1 ct. Recoatable Epoxy Primer @ 5.0 mils (125 microns) dft

*unless otherwise noted b				
Test Name	Test Method	Results		
Abrasion Resistance	ASTM D4060, CS17 wheel, 1000 cycles, 1 kg load	200 mg loss		
Accelerated Weathering - QUV ¹	ASTM D4587, QUV- A, 5,000 hours	Passes		
Adhesion	ASTM D4541	1050 psi		
Corrosion Weathering	ASTM D5894, 13 cycles, 4,368 hours	Rating 10 per ASTM D714 for Blistering; Rating 7 per ASTM D610 for Rusting		
Direct Impact Resistance	ASTM D2794	160 in. lbs.		
Dry Heat Resistance	ASTM D2485	250°F (121°C) (dis- colors)		
Flexibility	ASTM D522, 180° bend, 1" mandrel	Passes		
Moisture Condensa- tion Resistance	ASTM D4585, 100°F (38°C), 2000 hours	Passes, no cracking or delamination		
Pencil Hardness	ASTM D3363	3H		
Salt Fog Resistance ¹	ASTM B117, 5,600 hours	Passes, no cracking or delamination		
Slip Coefficient, Red Oxide**	AISC Specification for Structural Joints Using ASTM A325 or ASTM A490 Bolts	Class A, 0.50		
Surface Burning*	ASTM E84/NFPA 255	Flame Spread Index 15; Smoke Develop- ment Index 30		

*System tested (Report No. IM54.1157-02-01): Recoatable Epoxy Primer @ 4.6 mils (115 microns) dft Macropoxy 646 @ 5.0 mils (125 microns) dft

**Refer to Slip Certification document

Epoxy coatings may darken or yellow following application and curing. Provides performance comparable to products formulated to federal specifications: Mil-P-23377, Mil-P-53022

<u>Footnotes:</u> ¹ Acrolon 218 HS topcoat



& Marine Coatings

PART G B67A5
PART G B67H5
PART G B67R5
PART G B67WJ5000
PART H B67V5

LIGHT GRAY
TAN
RED OXIDE
WHITE
HARDENER

Revised: Sept 8, 2015

APPLICATION BULLETIN

4.45

APPLICATION PROCEDURES

Surface preparation must be completed as indicated.

Mix contents of each component thoroughly with low speed power agitation. Make certain no pigment remains on the bottom of the cans. Then combine one part by volume of Part G with one part by volume of Part H. Thoroughly agitate the mixture with power agitation. Allow the material to sweat-in as indicated. Re-stir before using.

If reducer solvent is used, add only after both components have been thoroughly mixed, after sweat-in.

Apply paint at the recommended film thickness and spreading rate as indicated below:

Recommended Spreading Rate per coat: Minimum Maximum Wet mils (microns) 6.0 (150) 9.0 (225) Dry mils (microns) 4.0* (100) 6.0* (150) ~Coverage sq ft/gal (m²/L) **175** (4.3) 260 (6.4) Theoretical coverage sq ft/qal 1040 (25.5) (m2/L) @ 1 mil / 25 microns dft *See Performance Tips section

NOTE: Brush or roll application may require multiple coats to achieve maximum film thickness and uniformity of appearance.

Drying Schedule @ 6.0 mils wet (150 microns):					
	@ 35°F/1.5°C	@ 77°F/25°C	@ 120°F/49°C		
		50% RH			
To touch:	1 hour	15 minutes	10 minutes		
Tack free:	2 hours	30 minutes	15 minutes		
To recoat:					
minimum:	6 hours	2 hours	30 minutes		
maximum:	1 year	1 year	1 year		
To cure:	14 days	14 days	2 days		
If maximum recoat time is exceeded, abrade surface before recoating.					
Drying time is temperature, humidity, and film thickness dependent.					
Pot Life:	8+ hours	8 hours	3 hours		
Sweat-in-time:	1 hour	30 minutes	10 minutes		

Application of coating above maximum or below minimum recommended spreading rate may adversely affect coating performance.

CLEAN UP INSTRUCTIONS

Clean spills and spatters immediately with Reducer #54, R7K54. Clean tools immediately after use with Reducer #54, R7K54. Follow manufacturer's safety recommendations when using any solvent.

DISCLAIMER

The information and recommendations set forth in this Product Data Sheet are based upon tests conducted by or on behalf of The Sherwin-Williams Company. Such information and recommendations set forth herein are subject to change and pertain to the product offered at the time of publication. Consult your Sherwin-Williams representative to obtain the most recent Product Data Information and Application Bulletin.

PERFORMANCE TIPS

Stripe coat all crevices, welds, and sharp angles to prevent early failure in these areas.

When using spray application, use a 50% overlap with each pass of the gun to avoid holidays, bare areas, and pinholes. If necessary, cross spray at a right angle.

Spreading rates are calculated on volume solids and do not include an application loss factor due to surface profile, roughness or porosity of the surface, skill and technique of the applicator, method of application, various surface irregularities, material lost during mixing, spillage, overthinning, climatic conditions, and excessive film build.

Excessive reduction of material can affect film build, appearance, and adhesion.

Do not apply the material beyond recommended pot life.

Do not mix previously catalyzed material with new.

In order to avoid blockage of spray equipment, clean equipment before use or before periods of extended downtime with Reducer #54, R7K54.

Material must be at least 50°F (10°C) prior to catalyzing.

Quik-Kick Epoxy Accelerator is acceptable for use. See data page 4.99 for details.

When coating over aluminum and galvanizing, recommended dft is 2-4 mils (50-100 microns).

Refer to Product Information sheet for additional performance characteristics and properties.

SAFETY PRECAUTIONS

Refer to the MSDS sheet before use.

Published technical data and instructions are subject to change without notice. Contact your Sherwin-Williams representative for additional technical data and instructions.

WARRANTY

The Sherwin-Williams Company warrants our products to be free of manufacturing defects in accord with applicable Sherwin-Williams quality control procedures. Liability for products proven defective, if any, is limited to replacement of the defective product or the refund of the purchase price paid for the defective product as determined by Sherwin-Williams. NO OTHER WARRANTY OR GUARANTEE OF ANY KIND IS MADE BY SHERWIN-WILLIAMS, EXPRESSED OR IMPLIED, STATUTORY, BY OPERATION OF LAW OR OTHERWISE, INCLUDING MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE.



Marine **Coatings**

PART G B67A5 PART G **B67H5** PART G **B67R5** PART G B67WJ5000 PART H B67V5

LIGHT GRAY TAN RED OXIDE WHITE HARDENER

Revised: Sept 8, 2015

APPLICATION BULLETIN

SURFACE PREPARATIONS

Surface must be clean, dry, and in sound condition. Remove all oil, dust, grease, dirt, loose rust, and other foreign material to ensure adequate adhesion.

Iron & Steel (atmospheric service)

Remove all oil and grease from surface by Solvent Cleaning per SSPC-SP1. Minimum surface preparation is Commercial Blast Cleaning per SSPC-SP6/NACE 3. For better performance, use Near White Metal Blast Cleaning per SSPC-SP10/NACE 2. Blast clean all surfaces using a sharp, angular abrasive for optimum surface profile (2 mils / 50 microns). Prime any bare steel the same day as it is cleaned.

Galvanized Steel

Allow to weather a minimum of six months prior to coating. Solvent Clean per SSPC-SP1. When weathering is not possible, or the surface has been treated with chromates or silicates, first Solvent Clean per SSPC-SP1 and apply a test patch. Allow paint to dry at least one week before testing adhesion. If adhesion is poor, brush blasting per SSPC-SP7 is necessary to remove these treatments. Rusty galvanizing requires a minimum of Hand Tool Cleaning per SSPC-SP2, prime the area the same day as cleaned.

In preparing galvanized steel substrates for the application of FIRETEX intumescent coating systems, Surface Preparation Specification SSPC-SP 16 must be followed obtaining a surface profile of minimum 1.5 mils (38 microns). Optimum surface profile will not exceed 2.0 mils (50 microns).

Previously Painted Surfaces

If in sound condition, clean the surface of all foreign material. Smooth, hard or glossy coatings and surfaces should be dulled by abrading the surface. Apply a test area, allowing paint to dry one week before testing adhesion. If adhesion is poor, or if this product attacks the previous finish, removal of the previous coating may be necessary. If paint is peeling or badly weathered, clean surface to sound substrate and treat as a new surface as above.

515, S. 🕰 S 7	April 19 11 11 11	_		1 - ダビント かっしょくり
APPI	ICATI	ON L	กมก	ITIONS

Temperature:

air and surface:

35°F (1.6°C) minimum, 140°F (60°C)

maximum

material:

50°F (10°C) minimum At least 5°F (2.8°C) above dew point

Relative humidity:

85% maximum

APPLICATION EQUIPMENT

The following is a guide. Changes in pressures and tip sizes may be needed for proper spray characteristics. Always purge spray equipment before use with listed reducer. Any reduction must be compliant with existing VOC regulations and compatible with the existing environmental and application conditions.

Reducer/Clean Up

Below 80°F (27°C)	Reducer #54, R7K54 or R7K111
	Reducer #100, R7K100, R7K104
	or R7K111
In California	Peducor P7V111

Airless Spray

Pressure	2400 psi
Hose	
Tip	017"
Filter	60 mesh

Reduction.....As needed up to 5% by volume

Brush

Brush	Natural Bristle
Reduction	Not recommended

Roller

Cover	3/8" - 1/2" woven with solvent resistant core
Reduction	Not recommended

Plural Component Spray ... Acceptable

Refer to April 2010 Technical Bulletin - "Application Guidelines for Macropoxy 646 & Recoatable Epoxy Primer Utilizing Plural Component Equipment"

If specific application equipment is not listed above, equivalent equipment may be substituted.

	Surface Preparation Standards				
	Condition of Surface	ISO 8501-1 BS7079:A1	Swedish Std. SIS055900	SSPC	NACE
White Metal Near White Metal Commercial Blast Brush-Off Blast		Sa 3 Sa 2.5 Sa 2 Sa 1	Sa 3 Sa 2.5 Sa 2 Sa 1	SP 5 SP 10 SP 6 SP 7 SP 2	1 2 3
Hand Tool Cleaning	Rusted Pitted & Rusted	ČŠt 2 D St 2	C St 2 D St 2	SP 2	4 -
Power Tool Cleaning	Rusted Pitted & Rusted	D St 3	C St 3 D St 3	SP 3 SP 3	<u>-</u>



Marine **Coatings**

PART G	B67A5
PART G	B67H5
PART G	B67R5
PART G	B67WJ5000
PART H	B67V5

LIGHT GRAY TAN RED OXIDE WHITE HARDENER

Revised: Sept 8, 2015

PRODUCT INFORMATION

4.45

RECOMMENDED SYSTEMS

4,130, 430,		701 LING	
		Dry Film Th	ickness / ct. (Microns)
Steel,	catalyzed epoxy topcoat:		
1 ct.	Recoatable Epoxy Primer	4.0-6.0	(100-150)
2 cts.	Tile-Clad HS Epoxy	2.5-4.0	(63-100)
	and clading Epoxy	2.0 7.0	(03-100)
Steel,	polyurethane topcoat:		
1 ct.	Recoatable Epoxy Primer	4.0-6.0	(100-150)
1-2 cts	. Hi-Solids Polyurethane	3.0-4.0	(75-100)
	,	0.00	(. 0 .00)
Steel,	acrylic epoxy topcoat:		
1 ct.	Recoatable Epoxy Primer	4.0-6.0	(100-150)
2 cts.	Water Based Catalyzed Epoxy	2.5-3.0	(63-75)
	, , ,		(,
Steel,	acrylic topcoat:		
1 ct.	Recoatable Epoxy Primer	4.0-6.0	(100-150)
2 cts.		2.5-4.0	(63-100)
	Coating		(00 100)
Galvar	nized:		
1 ct.	Recoatable Epoxy Primer	4.0-6.0	(100-150)
2 cts.	Tile-Clad HS Epoxy	2.5-4.0	(63-100)
			(55 150)
FIRETE	X ONLY:		

Steel &	Galvanized Substrates being	g primed for F	IRETEX only:
1 ct.	Recoatable Epoxy Primer	2.0-5.0	(50-125)

SURFACE PREPARATION

Surface must be clean, dry, and in sound condition. Remove all oil, dust, grease, dirt, loose rust, and other foreign material to ensure adequate adhesion.

Refer to product Application Bulletin for detailed surface preparation information.

Minimum recommended surface preparation:

Iron & Steel: SSPC-SP6/NACE 3, 2 mil (50 micron)

profile

Galvanizing*: SSPC-SP1

See Surface Preparations section on page 3 for application of FIRETEX intumescent coating systems

Surface Preparation Standards					
	Condition of Surface	ISO 8501-1 BS7079:A1	Swedish Std. SIS055900	SSPC	NACE
White Metal Near White Metal		Sa 3 Sa 2.5	Sa 3 Sa 2.5	SP 5 SP 10	1 2
Commercial Blast Brush-Off Blast		Sa 2 Sa 1	Sa 2 Sa 1	SP 6 SP 7	3
Hand Tool Cleaning	Rusted Pitted & Rusted	C St 2	C St 2	SP 2 SP 2	-
Power Tool Cleaning	Rusted Pitted & Rusted	Ĕ Šį š	C St 3 D St 3	SP 3	-
	TILEG & ITUSIEU	<u> </u>	Data	SP 3	

TINTING

Do not tint.

APPLICATION CONDITIONS

Temperature:

air and surface:

35°F (1.6°C) minimum, 140°F (60°C)

maximum

material: 50°F (10°C) minimum

At least 5°F (2.8°C) above dew point

Relative humidity:

85% maximum

Refer to product Application Bulletin for detailed application information.

ORDERING INFORMATION

Packaging:

Part H:

Part G: 1 gallon (3.78L) and 5 gallon (18.9L)

containers

1 gallon (3.78L) and 5 gallon (18.9L)

containers

Weight: 13.26 ± 0.2 lb/gal ; 1.6 Kg/L, mixed

SAFETY PRECAUTIONS

Refer to the MSDS sheet before use.

Published technical data and instructions are subject to change without notice. Contact your Sherwin-Williams representative for additional technical data and instructions.

DISCLAIMER

The systems listed above are representative of the product's use,

other systems may be appropriate.

The information and recommendations set forth in this Product Data Sheet are based upon tests conducted by or on behalf of The Sherwin-Williams Company. Such information and recommendations set forth herein are subject to change and pertain to the product offered at the time of publication. Consult your Sherwin-Williams representative to obtain the most recent Product Data Information and Application Bulletin,

WARRANTY

The Sherwin-Williams Company warrants our products to be free of manufacturing defects in accord with applicable Sherwin-Williams quality control procedures. Liability for products proven defective, if any, is limited to replacement of the defective product or the refund of the purchase price paid for the defective product as determined by Sherwin-Williams. NO OTHER WARRANTY OR GUARANTEE OF ANY KIND IS MADE BY SHERWIN-WILLIAMS, EXPRESSED OR IMPLIED, STATUTORY, BY OPERATION OF LAW OR OTHERWISE, INCLUDING MER-CHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE.

COMPANY: PACKAGING SERVICE CO., INC. PRODUCT IDENTITY: CROWN XYLOL (XYLENE)

NEW MSDS DATE: 12/3/2007

DATE: 12/3/07 PAGE 1 OF 5



MATERIAL SAFETY DATA SHEET

This Material Safety Data Sheet conforms to the requirements of ANSI Z400.1. THIS MSDS COMPLIES WITH 29 CFR 1910.1200 (HAZARD COMMUNICATION STANDARD). IMPORTANT: Read this MSDS before handling & disposing of this product. Pass this information on to employees, customers, & users of this product.

SECTION 1. IDENTIFICATION OF THE SUBSTANCE/PREPARATION AND COMPANY

PRODUCT IDENTITY: CROWN XYLOL (XYLENE)
COMPANY IDENTITY: PACKAGING SERVICE CO., INC.

COMPANY ADDRESS: 1904 MYKAWA ROAD PEARLAND, TX 77581 1-281-485-1458 1-800-424-9300

XYL001 SECTION 2. COMPOSITION/INFORMATION ON INGREDIENTS

CONTAINS:

75-85% MIXED XYLENES (1330-20-7)[215-535-7], 15-25% ETHYLBENZENE (100-41-4)[202-849-4] Number in parentheses is CAS #, number in brackets is European EC #.

This product is hazardous as defined in 29 CFR1910.1200, based on the following compositional information:

OSHA HAZARD COMPONENT

Flammable Xylenes; Ethylbenzene OSHA PEL;ACGIH TLV Xylenes; Ethylbenzene

Eye Irritant Xylene Possible Carcinogen Ethylbenzene

SECTION 3. HAZARDS IDENTIFICATION

RISK STATEMENTS:

Flammable Liquid

R36/37/38 Irritating to eyes, respiratory system and skin.

R20/65 Harmful by inhalation may cause lung damage if swallowed.

SAFETY STATEMENTS:

S16 Keep away from sources of ignition. No smoking.

S29 Do not empty into drains. S24/25 Avoid contact with skin and eyes.

INHALATION: High vapor/aerosol concentrations (attainable at elevated temperatures well above ambient) are irritating to the eyes and the respiratory tract, and may cause headaches, dizziness, anesthesia, drowsiness, unconsciousness, and other central nervous system effects, including death Negligible hazard at ambient temperature (-18 to 38 Deg C; 0 to 100 Deg F)

INGESTION: Small amounts of this product aspirated into the respiratory system during ingestion or vomiting may cause mild to severe pulmonary injury, possibly progressing to death. Low order of toxicity.

CHRONIC EFFECTS: This product contains ethylbenzene. The International Agency for Research on Cancer (IARC) has evaluated ethylbenzene and classified it as a possible human carcinogen (group 2B) based on sufficient evidence for carcinogenicity in experimental animals, but inadequate evidence for cancer in exposed humans.

SECTION 4. FIRST AID MEASURES

EYE CONTACT: For eyes, flush with plenty of water for 15 minutes & get medical attention.

SKIN CONTACT: In case of contact with skin immediately remove contaminated clothing. Wash thoroughly with soap & water. Wash contaminated clothing before reuse.

INHALATION: After high vapor exposure, remove to fresh air. If breathing is difficult, give oxygen. If breathing has stopped give artificial respiration.

COMPANY:

PACKAGING SERVICE CO., INC.

PRODUCT IDENTITY:

CROWN XYLOL (XYLENE)

NEW MSDS DATE: 12/3/2007

SWALLOWING: If swallowed, CALL A PHYSICIAN IMMEDIATELY! Do NOT induce vomiting. Have patient lie down & keep warm. Vomiting may lead to pneumonitis, which may be fatal.

DATE: 12/3/07

PAGE 2 OF 5

XYL001

SECTION 5. FIRE FIGHTING MEASURES

EXTINGUISHING MEDIA: NFPA Class B extinguishers (Carbon Dioxide or foam) for Class I C liquid fires.

FLASH POINT: 79 Deg F. METHOD: TCC ASTM D56 NOTE: Minimum LEL: 1.9 UEL: 12.3 @ 77 Deg F. NOTE: Approximate

AUTOIGNITION TEMP.: 932 Deg F. NOTE: Approximate

SPECIAL FIRE FIGHTING PROCEDURES: Water spray may be ineffective on fire but can protect fire fighters & cool closed containers. Shut off fuel to fire. Use foam or dry chemical to extinguish fire. Use fog nozzles if water is used. Do not enter confined fire-space without full bunker gear. Respiratory and eye protection required for fire fighting personnel. (Helmet with face shield, bunker coats, gloves & rubber boots). Use NIOSH approved positive-pressure self-contained breathing apparatus.

UNUSUAL EXPLOSION AND FIRE PROCEDURES FLAMMABLE!! VAPORS CAN CAUSE FLASH FIRE. This liquid is volatile and gives off invisible vapors. Keep container tightly closed. Isolate from oxidizers, heat, sparks, electric equipment & open flame. Closed containers may explode if exposed to extreme heat. Applying to hot surfaces requires special precautions. Empty container very hazardous! Continue all label precautions!

DECOMPOSITION PRODUCTS UNDER FIRE CONDITIONS: Furnes, smoke, and carbon monoxide.

SECTION 6. ACCIDENTAL RELEASE MEASURES

CONTAINMENT TECHNIQUES: Stop spill at source. Dike area & contain.

CLEAN-UP PROCEDURES: Clean up remainder with non-combustible absorbent materials. Mop up & dispose of. Persons without proper protection should be kept from area until cleaned up. If spilled on water, eliminate sources of ignition. Warn occupants and shipping in surrounding and downwind areas of fire and explosion hazard and request all to stay clear. Remove from surface with suitable adsorbents. If allowed by local authorities and environmental agencies, sinking and/or suitable dispersants may be used in non-confined waters. Consult an expert on disposal of recovered material and ensure conformity to local disposal regulations.

SECTION 7. HANDLING AND STORAGE

HANDLING: Isolate from oxidizers, heat, sparks, electric equipment & open flame. Use only with adequate ventilation. Avoid breathing of vapor or spray mist. Avoid prolonged or repeated contact with skin. Wear OSHA Standard goggles or face shield. Consult Safety Equipment Supplier. Wear gloves, apron & footwear impervious to this material. Wash clothing before reuse. Avoid free fall of liquid.

ELECTROSTATIC ACCUMULATION HAZARD. Ground containers when transferring. Do not flame cut, saw, drill, braze, or weld. Empty container very hazardous! Continue all label precautions!

STORAGE: Do not store above 49 C/120 F. Store large amounts in structures made for OSHA Class I C liquids Keep container tightly closed & upright when not in use to prevent leakage.
OSHA Class I C liquids

STORAGE TEMPERATURE

LOADING/UNLOADING TEMPERATURE

STORAGE/TRANSPORT PRESSURE mmHg:

Atmospheric

LOADING/UNLOADING VISCOSITY cSt: 0.7

SECTION 8. EXPOSURE CONTROLS/PERSONAL PROTECTION:

EXPOSURE CONTROLS: Ventilate to keep vapors of this material below 50 ppm. If over TLV, in accordance with 29 CFR 1910.134, use NIOSH approved positive-pressure self-contained breathing apparatus. Consult Safety Equipment Supplier. Use explosion-proof equipment.

VENTILATION:

LOCAL EXHAUST:

MECHANICAL (GENERAL):

SPECIAL:

OTHER:

Necessary

Acceptable

None

None

COMPANY:

PACKAGING SERVICE CO., INC.

PRODUCT IDENTITY: NEW MSDS DATE:

CROWN XYLOL (XYLENE)

12/3/2007

DATE: 12/3/07 PAGE 3 OF 5

PERSONAL PROTECTIONS: Wear OSHA Standard goggles or face shield. Consult Safety Equipment Supplier. Wear gloves, apron & footwear impervious to this material. Wash clothing before reuse.

WORK & HYGIENIC PRACTICES: Provide readily accessible eye wash stations & safety showers. Wash at end of each workshift & before eating, smoking or using the toilet. Promptly remove clothing that becomes contaminated. Destroy contaminated leather articles. Launder or discard contaminated clothing.

WORKPLACE EXPOSURE GUIDELINES

OSHA REGULATION 29CFR1910.1000 REQUIRES THE FOLLOWING PERMISSIBLE EXPOSURE LIMITS: A TWA of 100 ppm (435 mg/m3) and a STEL of 150 ppm (655 mg/m3) for Xylenes. A TWA of 100 ppm (435 mg/m3) and a STEL of 125 ppm (545 mg/m3) for Ethyl Benzene.

THE ACGIH RECOMMENDS THE FOLLOWING THRESHOLD LIMIT VALUES:

A TWA of 100 ppm (434 mg/m3) and a STEL of 150 ppm (651 mg/m3) for Xylene, with an A4 designation.

A TWA of 100 ppm (434 mg/m3) and a STEL of 125 ppm (543 mg/m3) for Ethyl Benzene with an A3 designation.

SECTION 9. PHYSICAL DATA

APPEARANCE: Liquid, Water-White ODOR: Aromatic **BOILING RANGE:** 136 140 142 C / 278 284 288 F **AUTO IGNITION TEMPERATURE:** 510 C / 950 F (Lowest Component) LOWER FLAMMABLE LIMIT IN AIR (% by vol): 1.1 FLASH POINT (TEST METHOD): 27 C / 81 F (TCC) FLAMMABILITY CLASSIFICATION: Class I C GRAVITY @ 60 F: API: 31.1 SPECIFIC GRAVITY (Water=1): .870 POUNDS/GALLON: 7.247 VOC'S (>0.44 Lbs/Sq in): 100.1 Vol. % / 871.0 g/L / 7.255 Lbs/Gal TOTAL VOC'S (TVOC): 100.0 Vol. % / 870.0 g/L / 7.247 Lbs/Gal NONEXEMPT VOC'S (CVOC): 100.0 Vol. % / 870.0 g/L / 7.247 Lbs/Gal HAZARDOUS AIR POLLUTANTS (HAPS): 100.0 Wt. % / 870.0 g/L / 7.247 Lbs/Gal VAPOR PRESSURE (mm of Hg)@20 C / 37 C 6.4 / 14.2 NONEXEMPT VOC PARTIAL PRESSURE (mm of Ha @ 20 C) 6.4 VAPOR DENSITY (air=1): 3.7 WATER ABSORPTION: Negligible REFRACTIVE INDEX: 1.496 FREEZING/ MELTING TEMP °F -31 **EVAPORATION RATE n-Bu Acetate=1** 0.8 - Approximate SOLUBILITY IN WATER, wt. % at Deg F: 0.02 at 77 Calculated VISCOSITY OF LIQUID, cSt at Deg F: 0.7 at 77 Approximate

SECTION 10. STABILITY & REACTIVITY

STABILITY: Stable

CONDITIONS TO AVOID: Isolate from oxidizers, heat, sparks, electric equipment & open flame.

MATERIALS TO AVOID: Isolate from strong oxidizers such as permanganates, chromates & peroxides, concentrated nitric and sulphuric acids, halogen, and molten sulphur. Temperatures above ambient.

HAZARDOUS DECOMPOSITION PRODUCTS: Carbon Monoxide, Carbon Dioxide from burning.

HAZARDOUS POLYMERIZATION: Will not occur.

COMPANY:

PACKAGING SERVICE CO., INC.

PRODUCT IDENTITY: NEW MSDS DATE: **CROWN XYLOL (XYLENE)**

12/3/2007

DATE: 12/3/07 PAGE 4 OF 5

SECTION 11. TOXICOLOGICAL INFORMATION

MATERIAL	CAS#	TWA (OSHA)	TLV (ACGIH)	HAP
Mixed Xylenes	1330-20-7	100 ppm	100 ppm A4	Yes
Ethylbenzene	100-41-4	100 ppm	100 ppm A3	Yes

In addition to EPA Hazardous Air Pollutants showing 'Yes' under "HAP" above, using manufacturers' data, based on EPA Method 311, the following EPA Hazardous Air Pollutants may be present in trace amounts (less than 0.1%): Benzene, Toluene, Cumene. Refer to Section 13 for additional potential health effects.

MATERIAL	CAS#	CEILING	STEL (OSHA/ACGIH)
Mixed Xylenes	1330-20-7	None Known	150 ppm
Ethylbenzene	100-41-4	None Known	125 ppm

ACUTE HAZARDS

EYE & SKIN CONTACT: Primary irritation to skin, defatting, dermatitis. Absorption thru skin increases exposure. Primary irritation to eyes, redness, tearing, blurred vision. Liquid can cause eye irritation. Wash thoroughly after handling.

INHALATION: Anesthetic. Irritates respiratory tract. Acute overexposure can cause serious nervous system depression. Vapor harmful. Acute overexposure can cause damage to kidneys, blood, nerves, liver & lungs.

SWALLOWING: Harmful or fatal if swallowed. Swallowing can cause abdominal irritation, nausea, vomiting & diarrhea.

SUBCHRONIC HAZARDS/CONDITIONS AGGREVATED

CONDITIONS AGGREVATED: Chronic overexposure can cause damage to kidneys, blood, nerves, liver & lungs. Persons with severe skin, liver or kidney problems should avoid use.

CHRONIC HAZARDS

CANCER, REPRODUCTIVE & OTHER CHRONIC HAZARDS: Potential Cancer Hazard based on tests with laboratory animals using Ethylbenzene. Overexposure may create cancer risk. Leukemia been reported in humans from Benzene. This product may contain less than 100 ppm of Benzene. Not considered hazardous in such low concentrations. Absorption thru skin may be harmful. Studies with laboratory animals indicate this product can cause damage to fetus.

SECTION 12. ECOLOGICAL INFORMATION

MAMMALIAN INFORMATION: MATERIAL	CAS#	LOWEST KNOWN LETHAL DOSE DATA
Xylene	1330-20-7	LOWEST KNOWN LD50 (ORAL) 4000.0 mg/kg(Rats)
Xylene	1330-20-7	LOWEST KNOWN LC50 (VAPORS) 5000 ppm (Mice)

AQUATIC ANIMAL INFORMATION: The most sensitive known marine group to any component of this product is: Fish are adversely affected by components of this product.

MOBILITY: This material is a mobile liquid.

DEGRADABILITY: This product is non-biodegradable.

ACCUMULATION: This product does not accumulate or biomagnify in the environment.

SECTION 13. DISPOSAL CONSIDERATIONS

Recycle / dispose of observing national, regional, state, provincial and local health, safety & pollution laws. If questions exist, contact the appropriate agencies.

COMPANY: PACKAGING SERVICE CO., INC. DATE: 12/3/07
PRODUCT IDENTITY: CROWN XYLOL (XYLENE) PAGE 5 OF 5

NEW MSDS DATE: 12/3/2007

SECTION 14. TRANSPORT INFORMATION

DOT SHIPPING NAME: UN 1307, Xylene, 3, PG III DRUM LABEL: (FLAMMABLE LIQUID)

49 CFR 173.150 allows "consumer commodity" quantities in packaging of one gallon or less to be reclassified as ORM-D

material.

IATA / ICAO: UN 1307, Xylene, 3, PG III

IMO / IMDG: UN 1307, Xylene, 3, UN1307, PG III

If >118 pounds of this product is in one container, the RQ is exceeded.

EMERGENCY RESPONSE GUIDEBOOK NUMBER: 130

SECTION 15. REGULATORY INFORMATION

STATE REQULATIONS: CALIFORNIA PROPOSITION 65: This product contains the following chemical known to the State of California to cause cancer: Ethylbenzene

TSCA: Components of this product are listed on the TSCA Inventory. Clean Water Act/Oil Pollution Act: This product is classified as an oil under Section 311 of the Clean Water Act (40 CFR 110) and the Oil Pollution Act of 1990. Discharge or spills which produce a visible sheen on either surface water, or in waterways/sewers which lead to surface water, must be reported to the National Response Center at 800-424-8802.

CERCLA: If the reportable quantity of this product is accidentally spilled, the incident is subject to the provisions of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) and must be reported to the National Response Center by calling 800-424-8802. The reportable spill quantity of this product is 118 pounds. It contains: Xylene, Ethylbenzene.

SARA TITLE III: Under the provisions of Title III, Sections 311/312 of the Superfund Amendments and Reauthorization Act, this product is classified into the following hazard categories: Immediate health, Delayed Health, Fire. This information may be subject to the provisions of the Community Right-to-Know Reporting Requirements (40 CFR 370) if threshold quantity criteria are met. This product contains the following Section 313 Reportable Ingredients:

COMPONENT	CAS#	<u>MAX. %</u>
Xylene	1330-20-7	85.0
Ethyl Benzene	100-41-4	25.0

INTERNATIONAL REGULATIONS: The components of this product are listed on the chemical inventories of the following countries: Australia, Canada, Europe (EINECS), Japan, Korea, United Kingdom.

SECTION 16. OTHER INFORMATION

HAZARD RATINGS:

HEALTH (NFPA): 2 HEALTH (HMIS): 2 FLAMMABILITY: 3 REACTIVITY: 0

This information is intended solely for the use of individuals trained in the NFPA & HMIS hazard rating systems.

EMPLOYEE TRAINING: Employees should be made aware of all hazards of this material (as stated in this MSDS) before handling it.

NOTICE: The supplier disclaims all expressed or implied warranties of merchantability or fitness for a specific use, with respect to the product or the information provided herein, except for conformation to contracted specifications. All information appearing herein is based upon data obtained from manufacturers and/or recognized technical sources. While the information is believed to be accurate, we make no representations as to its accuracy or sufficiency. Conditions of use are beyond our control, and therefore users are responsible for verifying the data under their own operating conditions to determine whether the product is suitable for their particular purposes and they assume all risks of their use, handling, and disposal of the product. Users also assume all risks in regards to the publication or use of, or reliance upon, information contained herein. This information relates only to the product designated herein, and does not relate to its use in combination with any other material or process. Unless revised this MSDS is effective until 12/3/2010.

7 (Ypages)

MATERIAL SAFETY DATA SHEET

R7K54 07 00

DATE OF PREPARATION

Dec 12, 2014

SECTION 1 — PRODUCT AND COMPANY IDENTIFICATION

PRODUCT NUMBER

R7K54

PRODUCT NAME

Reducer No. 54

MANUFACTURER'S NAME

THE SHERWIN-WILLIAMS COMPANY 101 Prospect Avenue N.W. Cleveland, OH 44115

Telephone Numbers and Websites

ereprione numbers and websites	
Product Information	(800) 524-5979 www.sherwin-williams.com
Regulatory Information	(216) 566-2902 www.paintdocs.com
Medical Emergency	(216) 566-2917
Transportation Emergency*	(800) 424-9300
*for Chemical Emergency C	ONLY (spill, leak, fire, exposure, or accident)

																			ΙE		

% by Weight	CAS Number	Ingredient	Units	Vapor Pressure
4	100-41-4	Ethylbenzene		
		ACGIH TLV	20 PPM	7.1 mm
		OSHA PEL	100 PPM	
		OSHA PEL	125 PPM STEL	
22	1330-20-7	Xylene		
		ACGIH TLV	100 PPM	5.9 mm
		ACGIH TLV	150 PPM STEL	
		OSHA PEL	100 PPM	
		OSHA PEL	150 PPM STEL	
23	64-17-5	Ethanol		
		ACGIH TLV	1000 PPM	44 mm
		OSHA PEL	1000 PPM	
51	108-10-1	Methyl Isobutyl Ketone		
		ACGIH TLV	50 PPM	16 mm
		ACGIH TLV	75 PPM STEL	
		OSHA PEL	50 PPM	
		OSHA PEL	75 PPM STEL	

SECTION 3 — HAZARDS IDENTIFICATION

ROUTES OF EXPOSURE

INHALATION of vapor or spray mist.

EYE or SKIN contact with the product, vapor or spray mist.

Contains alcohols and acetates which can be absorbed through the skin.

EFFECTS OF OVEREXPOSURE

EYES: Irritation.

SKIN: Prolonged or repeated exposure may cause irritation.

INHALATION: Irritation of the upper respiratory system.

May cause nervous system depression. Extreme overexposure may result in unconsciousness and possibly death.

Prolonged overexposure to hazardous ingredients in Section 2 may cause adverse chronic effects to the following organs or systems:

• the liver

- the urinary system
- the reproductive system

SIGNS AND SYMPTOMS OF OVEREXPOSURE

Headache, dizziness, nausea, and loss of coordination are indications of excessive exposure to vapors or spray mists.

HMIS Codes
Health 2*
Flammability 3
Reactivity 0

Redness and itching or burning sensation may indicate eye or excessive skin exposure.

MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE

None generally recognized.

CANCER INFORMATION

For complete discussion of toxicology data refer to Section 11.

SECTION 4 — FIRST AID MEASURES

EYES: Flush eyes with large amounts of water for 15 minutes. Get medical attention.

SKIN: Wash affected area thoroughly with soap and water.

Remove contaminated clothing and launder before re-use.

INHALATION: If affected, remove from exposure. Restore breathing. Keep warm and quiet.

INGESTION: Do not induce vomiting. Get medical attention immediately.

SECTION 5 — FIRE FIGHTING MEASURES

FLASH POINT LEL UEL FLAMMABILITY CLASSIFICATION

55 °F PMCC 1.0 19.0 RED LABEL -- Flammable, Flash below 100 °F (38 °C)

EXTINGUISHING MEDIA

Carbon Dioxide, Dry Chemical, Foam

UNUSUAL FIRE AND EXPLOSION HAZARDS

Closed containers may explode when exposed to extreme heat.

Application to hot surfaces requires special precautions.

During emergency conditions overexposure to decomposition products may cause a health hazard. Symptoms may not be immediately apparent. Obtain medical attention.

SPECIAL FIRE FIGHTING PROCEDURES

Full protective equipment including self-contained breathing apparatus should be used.

Water spray may be ineffective. If water is used, fog nozzles are preferable. Water may be used to cool closed containers to prevent pressure build-up and possible autoignition or explosion when exposed to extreme heat.

SECTION 6 — ACCIDENTAL RELEASE MEASURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Remove all sources of ignition. Ventilate the area.

Remove with inert absorbent.

SECTION 7 — HANDLING AND STORAGE

STORAGE CATEGORY

DOL Storage Class IB

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE

Contents are FLAMMABLE. Keep away from heat, sparks, and open flame.

During use and until all vapors are gone: Keep area ventilated - Do not smoke - Extinguish all flames, pilot lights, and heaters - Turn off stoves, electric tools and appliances, and any other sources of ignition.

Consult NFPA Code. Use approved Bonding and Grounding procedures.

Keep container closed when not in use. Transfer only to approved containers with complete and appropriate labeling. Do not take internally. Keep out of the reach of children.

SECTION 8 — EXPOSURE CONTROLS/PERSONAL PROTECTION

PRECAUTIONS TO BE TAKEN IN USE

Use only with adequate ventilation.

Avoid contact with skin and eyes. Avoid breathing vapor and spray mist.

Wash hands after using.

VENTILATION

Local exhaust preferable. General exhaust acceptable if the exposure to materials in Section 2 is maintained below applicable exposure limits. Refer to OSHA Standards 1910.94, 1910.107, 1910.108.

RESPIRATORY PROTECTION

If personal exposure cannot be controlled below applicable limits by ventilation, wear a properly fitted organic vapor/particulate respirator approved by NIOSH/MSHA for protection against materials in Section 2.

PROTECTIVE GLOVES

Wear gloves which are recommended by glove supplier for protection against materials in Section 2.

EYE PROTECTION

Wear safety spectacles with unperforated sideshields.

OTHER PROTECTIVE EQUIPMENT

Use of barrier cream on exposed skin is recommended.

OTHER PRECAUTIONS

Intentional misuse by deliberately concentrating and inhaling the contents can be harmful or fatal.

SECTION 14 — TRANSPORT INFORMATION

Multi-modal shipping descriptions are provided for informational purposes and do not consider container sizes. The presence of a shipping description for a particular mode of transport (ocean, air, etc.), does not indicate that the product is packaged suitably for that mode of transport. All packaging must be reviewed for suitability prior to shipment, and compliance with the applicable regulations is the sole responsibility of the person offering the product for transport.

US Ground (DOT)

5 Liters (1.3 Gallons) and Less may be Classed as LTD. QTY. (PAINT OR RELATED).

Larger Containers are Regulated as:

UN1263, PAINT RELATED MATERIAL, 3, PG II, (ERG#128)

DOT (Dept of Transportation) Hazardous Substances & Reportable Quantities

Ethylbenzene 1000 lb RQ

Methyl isobutyl ketone 5000 lb RQ

Xylenes (isomers and mixture) 100 lb RQ

Bulk Containers may be Shipped as (check reportable quantities):

RQ, UN1263, PAINT RELATED MATERIAL, 3, PG II, (XYLENES (ISOMERS AND MIXTURE)), (ERG#128)

Canada (TDG)

UN1263, PAINT RELATED MATERIAL, CLASS 3, PG II, LIMITED QUANTITY, (ERG#128)

IMO

5 Liters (1.3 Gallons) and Less may be Shipped as Limited Quantity. UN1263, PAINT RELATED MATERIAL, CLASS 3, PG II, (13 C c.c.), EmS F-E, S-E

IATA/ICAO

UN1263, PAINT RELATED MATERIAL, 3, PG II

SECTION 15 — REGULATORY INFORMATION

SARA 313 (40 CFR 372.65C) SUPPLIER NOTIFICATION

CAS No.	CHEMICAL/COMPOUND	% by WT	% Element
100-41-4	Ethylbenzene	4	
1330-20-7	Xylene	22	
108-10-1	Methyl Isobutyl Ketone	51	

CALIFORNIA PROPOSITION 65

WARNING: This product contains chemicals known to the State of California to cause cancer and birth defects or other reproductive harm. TSCA CERTIFICATION

All chemicals in this product are listed, or are exempt from listing, on the TSCA Inventory.

SECTION 16 — OTHER INFORMATION

This product has been classified in accordance with the hazard criteria of the Canadian Controlled Products Regulations (CPR) and the MSDS contains all of the information required by the CPR.

The above information pertains to this product as currently formulated, and is based on the information available at this time. Addition of reducers or other additives to this product may substantially alter the composition and hazards of the product. Since conditions of use are outside our control, we make no warranties, express or implied, and assume no liability in connection with any use of this information.

question # 16

SDS

Safety Data Sheet

LANDA°

Phosphatizer

MSDS Number: L914472

Revision Date: April 10, 2014

Page 1 of 5

PRODUCT AND COMPANY IDENTIFICATION

Manufacturer

Kärcher North America, Inc. 325 South Price Road Chandler, AZ 85224

Phone:

360-833-1600

Fax: Email: 360-833-9200 info@karcherna.com

Web:

www.karcher.com

Product Name: Revision Date:

Phosphatizer April 10, 2014 44-36B

Version: MSDS Number:

L914472

In case of emergency: INFOTRAC 1-800-535-5053 International 1-352-323-3500

HAZARDS IDENTIFICATION

Route of Entry:

Eye; Skin; Inhalation

Target Organs:

Eye; Skin; Respiratory system

Inhalation:

Respiratory tract irritation may occur with exposure to a large amount of material.

Skin Contact:

May cause irritation, tearing and redness.


Eye Contact:

Irritating to eyes; eye damage may occur.

Ingestion:


Small amounts swallowed incidental to normal handling operations are not likely to cause injury; swallowing amounts larger than that may cause injury.

NFPA: HMIS III:



Health = 2, Fire = 1, Reactivity = 0 H2/F1/PH0





GHS Classifications:

Health, Acute toxicity, 5 Oral Health, Skin corrosion/irritation, 3

Safety Data Sheet



Phosphatizer

MSDS Number: L914472

Revision Date: April 10, 2014

Page 2 of 5

Health, Serious Eye Damage/Eye Irritation, 2 B

GHS Phrases:

Warning, H303 - May be harmful if swallowed Warning, H316 - Causes mild skin irritation Warning, H320 - Causes eye irritation

GHS Precautionary Statements:

Wash thoroughly after handling.

Wear protective gloves/protective clothing/eye protection/face protection.

IF IN EYES: Rinse continuously with water for several minutes. Remove contact lenses if present and easy to do.

Continue rinsing.

Call a POISON CENTER or doctor/physician if you feel unwell.

If eye irritation persists: Get medical advice/attention.

GHS PICTOGRAMS: No GHS Pictograms

HAZARDS IDENTIFICATION

Ingredients:

CAS # Percentage	Chemical Name
144-62-7 <0.2%	Oxalic acid
111-76-2 <3%	Ethylene glycol monobutyl ether
7664-38-2 <2%	Phosphoric acid

OSHA Regulatory Status:

This SDS contains valuable information critical to the safe handling and proper use of this product. This SDS should be retained and available for employees and other users of this product.

4 FIRST AID MEASURES

Inhalation:

If symptoms develop, move victim to fresh air. If symptoms persist, obtain medical attention.

Skin Contact:

Wash with soap and water. If irritation persists consult medical personnel.

Eye Contact:

Immediately flush eyes with large amounts of water for at least 15 minutes, lifting eyelids occasionally to facilitate

irrigation. Get immediate medical attention.

Ingestion:

If swallowed, DO NOT induce vomiting unless directed to do so by medical personnel. If injured party is conscious,

give two glasses of water. Seek medical attention.

5 FIRE FIGHTING MEASURES

Flash Point:

100 ° C / 212 ° F

Flash Point Method:

Closed Cup

Wear self-contained breathing apparatus and other protective clothing. Use any standard agent - choose the one most appropriate for type of surrounding fire.

Safety Data Sheet



Phosphatizer

MSDS Number: L914472

Revision Date: April 10, 2014

Page 3 of 5

6

ACCIDENTAL RELEASE MEASURES

Isolate area; keep unnecessary personnel away. Do not discharge into drains. Ventilate closed spaces before entering. Prevent further leakage or spillage if safe to do so. Prevent entry into waterways, sewers, basements or confined areas. Wear appropriate protective equipment and clothing during cleanup. Use a non-combustible material like vermiculite, sand or earth to soak up the product and place into a container for later disposal.

7

HANDLING AND STORAGE

Handling Precautions:

Avoid contact with eyes, skin, or clothing. Wash thoroughly after handling.

Storage Requirements:

Store out of reach of children; keep container closed; store in a cool, well-ventilated place.

EXPOSURE CONTROLS/PERSONAL PROTECTION

Engineering Controls:

All ventilation should be designed in accordance with OSHA standard (29 CFR 1910.94).

Personal Protective Equip:

HMIS PP, B | Safety Glasses, Gloves

.Ethylene glycol butyl ether 111-76-2 OSHA PEL 50 ppm - 240 mg/m3

Phosphoric Acid 7664-38-2 OSHA PEL 1 mg/m3

Personal protective equipment should be selected for individual applications and should consider factors which affect exposure potential, such as handling practices, chemical concentrations and ventilation. It is ultimately the responsibility of the employer to follow regulatory guidelines established by local authorities.

e

PHYSICAL AND CHEMICAL PROPERTIES

Appearance:

Clear colorless

Physical State:

Liquid

Odor:

Detergent - Solvent

Spec Grav./Density: pH:

9.34 lb/gal 3.08 as is Solubility:

Soluble

10

STABILITY AND REACTIVITY

Stability:

Product is stable under normal conditions. None Known

Conditions to Avoid: Materials to Avoid:

None Known

Hazardous Decomposition:

Exposure to fire may liberate carbon dioxide, carbon monoxide, organic acids, and other unidentified

thermal decomposition products from this product or its packaging.

Hazardous Polymerization:

Will not occur

20

TOXICOLOGICAL INFORMATION

Toxicity Data:

Oxalic Acid 144-62-7

Oral (LD 50): Not listed on RTECS

Safety Data Sheet



Phosphatizer

MSDS Number: L914472

Revision Date: April 10, 2014

Page 4 of 5

Intraperitoneal (injection) 270 mg/kg - Mouse

Inhalation (LC 50): Not listed on RTECS

Skin irritation: Mild

Eye irritation: Severe

Sensitation: Not considered an occupational sensitizer

Ethylene glycol butyl ether 111-76-2

Oral (LD 50): 917 mg/kg - Rat

Inhalation (LC 50): 2900 mg/m3/7H - Rat

Skin irritation: Mild Eye irritation: Mild

Sensitation: Not considered an occupational sensitizer

Phosphoric Acid 7664-38-2

Oral (LD 50): 1200 mg/kg - Rat

Inhalation (LC 50): 25.5 mg/m3 - rat

Skin irritation: Severe Eye irritation: Severe

Sensitation: Not considered an occupational sensitizer

12

ECOLOGICAL INFORMATION

On the basis of available information, this material is not expected to produce any significant environmental effects when recommended use instructions are followed.

13

DISPOSAL CONSIDERATIONS

Recommendation: consultation with the disposal agency and the relevant authorities; cleansing agent is water.

121

TRANSPORT INFORMATION

Ship in accordance with 49 CFR parts 100-185. Non-hazardous for air, sea and road freight.

Safety Data Sheet



Phosphatizer

MSDS Number: L914472

Revision Date: April 10, 2014

Page 5 of 5

15

REGULATORY INFORMATION

COMPONENT / (CAS/PERCENT) / CODES

*Oxalic acid (144627 <0.2%) MASS, OSHAWAC, PA, TSCA, TXAIR, WHMIS

- *Ethylene glycol monobutyl ether (111762 <3%) MASS, OSHAWAC, PA, TSCA, TXAIR, WHMIS
- *Phosphoric acid (7664382 <2%) CERCLA, CSWHS, EPCRAWPC, MASS, NJHS, OSHAWAC, SARA313, TSCA, TXAIR, WHMIS

REGULATORY KEY DESCRIPTIONS

All components are listed on TSCA

CERCLA = Superfund clean up substance
CSWHS = Clean Water Act Hazardous substances
EPCRAWPC = EPCRA Water Priority Chemicals
MASS = MA Massachusetts Hazardous Substances List
NJHS = NJ Right-to-Know Hazardous Substances
OSHAWAC = OSHA Workplace Air Contaminants
PA = PA Right-To-Know List of Hazardous Substances
SARA313 = SARA 313 Title III Toxic Chemicals
TXAIR = TX Air Contaminants with Health Effects Screening Level
WHMIS = Workplace Haz Mat Info Sys Canada

16

OTHER INFORMATION

This document is prepared in accordance with 29 CFR 1910.1200. The purpose of this section is to ensure that the hazards of all chemicals produced or imported are evaluated, and that information concerning their hazards is transmitted to employers and employees.

All information appearing herein is based upon data obtained from the raw material manufacturer and/or recognized technical sources. While the information above is believed to be true and accurate, the author makes no representations as to its accuracy or sufficiency. Conditions of use are beyond the manufacturer's control; therefore the users are responsible to verify this data under their own particular conditions, applications and regulations to determine if the product is suitable for their particular purposes. The users assume all risks of product use, handling, disposal, reliance upon, publication or use of the information contained herein. This information applies only to the product designated above and does not necessarily apply to its use in combination with other materials, products, chemical compounds, structures or processes.

Prepared by: EHS Manager